

July 26, 2013

SW Cole Engineering  
286 Portland Road  
Gray, ME 04039

ATTN: Roger Domingo

RE: Job #08-0494.2, Commercial and Maple Street Mixed Use, Portland, ME  
RTD 13-1020

Dear Sir,

As requested, an Inspection was performed at the Commercial and Maple Street Mixed Use Project located in Portland, Maine on July 15, 2013.

The inspection consisted of an in-process Visual Inspection of welds, bolted connections, joist and decking.

**6<sup>th</sup> Floor Grid Line 1 – 7, G - K**

All bolted connections, brace welds, joist and deck were inspected and found to be acceptable.

**Roof Grid Line 1 – 7, G - K**

All bolted connections, brace welds, joist and deck were inspected and found to be acceptable.

**2<sup>nd</sup> Floor Grid Line 4 – 8, A - G**

Column anchor bolts still in-progress.

Column to beam and beam to beam high strength A325 bolted connections 40% complete.


HSS diagonal wind brace connections 20% complete.

No joist or deck installed at this time.

The inspection was performed in accordance with AWS D1.1:2010, AWS D1.3, AISC 360-10 and SJI.

If I can be of further assistance please do not hesitate to call.

Respectfully,



Robert H. Parechanian, Jr.  
CWI #90100111



Robert H Parechanian, Jr.  
CWI 90100111  
QC1 EXP. 10/1/2014