

Report No. SI-002

Date: May 30, 2013
Project: Portland Marriott SWCE# 08-0494.2
Project Number: 13018
Time at Site: 10:00 am – 10:45 am
Weather: Sunny, 70's °F
Present at Site: Matthew J. Miller, P.E. (M2SE)

On Thursday May 30, 2013, I visited the site to inspect structural steel erection for general frame geometry and proper application of structural details.

Area of Observation: Second and Third Floor Framing - Grid Lines G-K Lines 1-8

Observations:

- At the time of our visit the work observed was in conformance with the structural drawings.