

Report No. SI-004

Date: August 20, 2013
Project: Portland Marriott
Project Number: 13018
Time at Site: 2:00 pm – 3:00 pm
Weather: Sunny, upper 70's °F
Present at Site: Matthew J. Miller, P.E. (M2SE)

On Tuesday, August 20, 2013, I visited the site to inspect structural steel erection for general frame geometry and proper application of structural details.

Area of Observation: 2nd through 6th Floor Framing and Roof Framing - Grid Lines A-G Lines 4-8

Observations:

- Structural Steel erection in the areas observed was substantially complete. The work observed was in conformance with the contract documents.