

<b>OBSERVATION REPORT</b>
Rough Carpentry

<b>Date:</b>	12-29-11
<b>Time:</b>	2:00 PM
<b>Temp:</b>	35 F
<b>Weather:</b>	Sunny

<b>Project:</b>	International Marine Terminal (Office Building)
<b>Location:</b>	Portland, Maine
<b>Becker Job No:</b>	2402.01

**Observation Location:** Sip installation in progress, wall sheathing complete.

	Satisfactory	Un-Satisfactory	Not Completed	Not Applicable	Comments
Member Sizes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Material Quality	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Bearing Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Connections	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	shearwall hold downs & light gage straps not yet installed
Nailing Pattern	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Bridging/Bracing	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Stud blocking in progress
Other:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	See below
Other:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

**Notes:**

SIPS not provided over exterior entry, two locations. Discussed with GC that panels could be field built in these locations as spans are relatively short. Panels to consist of 2x6 rafters at 12" o.c.

**Signed:** Dan S. Burne, P.E.