CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Inspection Date

Inspector

Owner/Manager

LA	LAMOUR RUSSELL & SYLVIE D JTS				Marland Wing			11/03/2005	
Locatation CBL			Status			Inspection Type			
27	STATE ST	044 B010001		Re-Inspe	Re-Inspect 30 Days		Complaint-Inspection		
	Code	Int/Ext			Floor	Unit No.	Area	Compliance Date	
1)	6-113.5		of lighting fixtures	ose					
2)	Violation: Notes:	Maintenance of plumbing fixtures. Kitchen sink garbage disposal inoperative							
3)	6-108.2 Violation: Notes:		erior floors, walls, ceilings and doors ceiling sign of leakage		2	Left	Kitchen		
4)	6-108.2	Interior Interior floors, walls, ceilings and doors Hall ceiling shows signs of leakage		2	Hall	Hall			
5)		Exterior wind	dows, doors and sk rindows	ylights					
6)			of lighting fixtures	n					
7)	Violation: Notes:	Exterior on: Foundations cellars, exterior walls, re Missing siding		lls, roofs	3		Rear wall		
8)	6-108.1 Violation: Notes:	Exterior Foundations cellars, exterior walls, roofs Rotted trim boards		lls, roofs	3		Rear wall		
9)	6-113.5	Maintenance Inoperative li	of lighting fixtures ght fixtures						
10)	Interior Violation: Interior floors, walls, ceilings and do Notes: Missing plaster in rear hall		d doors	1,2,3		Rear Hall			

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date	
LAMOUR RUSSELL & SYLV	IE D JTS	Marland Wing	11/03/2005	
Locatation	CBL	Status	Inspection Type	
27 STATE ST	044 B010001	Re-Inspect 30 Days	Complaint-Inspection	

11) 6-108.4

Stairways, stairwells, stairs, porches.

Rear hall stairs broken boards.