## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

October 12, 2017

Responsible Party 1:				
CBPC HOLDINGS LLC				
PO BOX 4182				
PORTLAND, ME 04101				
Location	CBL	<b>Inspection Date</b>		
Location 33 STATE ST	CBL 044 B016001	Inspection Date 9/15/2017		
		-		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 10/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. First and Third floor units.	//
NFPA 101- 31.3.7 FLOOR/ CEILINGS ASSEMBLY NOT SMOKE-TIGHT; In buildings other than those meeting the requirements of 31.3.7.1, 31.3.7.2, 31.3.7.3, 31.3.7.4, or 31.3.7.5, in addition to the following criteria to be met. Basement furnace room.	//
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6.  Second floor unit.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  Second floor unit.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.

Violation		Proposed Date of Completion
electrical equipment, including bush not be damaged or contaminated b abrasives, or corrosive residues. The	OSED WIRING CONNECTIONS; Internal parts of pars, wiring terminals, insulators, and other surfaces, shall by foreign materials such as paint, plaster, cleaners, nere shall be no damaged parts that may adversely affect gth of the equipment such as parts that are broken; bent; pemical reaction, or overheating.	//
31.3.2.1.1 shall be protected as ind	OTECTION REQUIRED; The areas described in Table icated: Boiler and fuel-fired heater rooms serving more in separation/protection is 1 hour or sprinklers)	//
	RE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 vertical shafts (including stairways, exits, and refuse hour.	//
FINAL DATE OF COMPLETED VIOLATION(S)		//
FIRE PREVENTION BUREAU RE-	INSPECTION OF COMPLETED VIOLATION(S)	//
understand that I must contact the is entirely within the Bureau's did I further understand that it is my have been remedied to do so. My violations have not been remedied If I fail to comply with this agree	y responsibility to schedule a reinspection of my proper y failure to schedule a reinspection shall be deemed an	est an extension, which ty once the violations admission that the unt to the City of
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	<u></u>