

CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
 Portland, Maine 04101

Inspection Violations

Owner/Manager CAMPBELL JOHN S TRUSTEE		Inspector Marland Wing	Inspection Date 2/8/2005
Location 22 STATE ST	CBL 044 C001001	Status Re-Inspect 30 Days	Inspection Type Complaint-Housing Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-108.2	Interior	1	right ap	Kitchen	
Violation:	Interior floors, walls, ceilings and doors				
Notes:	Kitchen ceiling missing tiles				
2) 6-116.5	Interior	1	right ap	Various locations	
Violation:	Fire Protection				
Notes:	missing hard wired smoke detector				
3) 6-108.3	Interior	2	lft apt	Kitchen	
Violation:	Exterior windows, doors and skylights				
Notes:	kitchen window broken glass				
4) 6-113.5	Interior	2	lft apt	Kitchen	
Violation:	Maintenance of lighting fixtures				
Notes:	kitchen wall missing receptacle cover				
5) 6-108.2	Interior	2	lft apt	Living Room	
Violation:	Interior floors, walls, ceilings and doors				
Notes:	Window missing storm & screen				
6) 6-108.2	Interior	2	lft apt	Bathroom	
Violation:	Interior floors, walls, ceilings and doors				
Notes:	bathroom door missing				
7) 6-108.4	Interior	3	lft apt	Stairways	
Violation:	Stairways, stairwells, stairs, porches.				
Notes:	stairway missing baluster				
8) 6-111.4	Interior	2	lft apt	Bathroom	
Violation:	Maintenance of plumbing fixtures.				
Notes:	cracked tank				

Comments: