CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date	
LOW INCOME PROPERTIES LLC		Marland Wing	6/28/2005	
Locatation	CBL	Status	Inspection Type	
36 STATE ST	044 C013001	Re-Inspect 30 Days	Complaint-	

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1)	6-108.2	Interior	3	apt 9	Living Room	_
	Violation:	Interior floors, walls, ceilings and doors				
	Notes:	Living room ceiling & wall peeling paint				
2)	6-108.2	Interior	3	apt 9	Bathroom	
	Violation:	Interior floors, walls, ceilings and doors				
	Notes:	Bathroom flr rotted board				
3)	6-108.2	Interior	3	apt 9	Hallway	
	Violation:	Interior floors, walls, ceilings and doors			-	
	Notes:	Hallway ceiling signs of leakage				

Comments: