

Portland, Maine



Yes. Life's good here.

Danielle P. West-Chuhta
Corporation Counsel

Anne M. Torregrossa
Associate Counsel

Michael I. Goldman
Associate Counsel

July 14, 2016

NOTICE OF INTENT TO PROSECUTE

Judith K. Gideon
38 Vesper Street
Scarborough, Maine 04074

RE: 97 Danforth Street
CBL044 F002001

To Whom it May Concern,

Please see the attached Inspection Violations. The City of Portland Fire Department has referred this matter to me for prosecution. In order to avoid prosecution, you must submit to Fire Prevention Bureau a plan of action to remedy the violations no later than **July 29, 2016**.

**YOUR FAILURE TO SUBMIT A PLAN OF ACTION
WITHIN THE TIMEFRAME PROVIDED WILL RESULT IN
LEGAL ACTION AND THE IMPOSITION OF CIVIL PENALTIES.**

Please feel free to contact Tori Ross of the Fire Prevention Bureau at (207)874-8400 with any questions. I look forward to your anticipated cooperation and appreciate your efforts to help keep the citizens of Portland safe.

Sincerely,

Anne M. Torregrossa
Associate Corporation Counsel
City of Portland

**CITY OF PORTLAND
PORTLAND FIRE DEPARTMENT**

380 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager Gideon Judith Kelly		Inspector Steven Hall		Inspection Date 7/7/2016	
Location 97 Danforth	CBL 044 F002001	Status Failed		Inspection Type Fire Company-FP Routine Inspec	

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 89.05					
Violation:	NFPA 1 EXCESSIVE/DISORDERLY STORAGE; REFERENCE NFPA 1 FOR EXCESSIVE FUEL-LOAD.				
Notes:	STORAGE IN STAIRWELLS				
2) 80.37					
Violation:	NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; REFER TO NFPA 101- TABLE 8.3.4.2 THAT STATES FIRE DOOR ASSEMBLIES FOR VERTICAL SHAFTS (INCLUDING STAIRWAYS, EXITS, AND REFUSE CHUTES) ARE RATED AND REQUIRED FOR 1 HOUR.				
Notes:	NEED FIRE DOORS				

Comments: