
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager 167-169 DANFORTH STREET		Inspector Marland Wing	Inspection Date 5/11/2005
Location 167 DANFORTH ST	CBL 044 I001001	Status Re-Inspect 30 Days	Inspection Type Complaint-Housing Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-108.1	Exterior	1, 2, &3		Various locations	
Violation: Foundations cellars, exterior walls, roofs					
Notes: Front wall missing bricks & Motar					
2) 6-108.1	Exterior	1, 2, &3		Various locations	
Violation: Foundations cellars, exterior walls, roofs					
Notes: Front wall granite lintels cracked & missing					

Comments: