CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

March 16, 2017

Responsible Party 1:				
Provost Ezra				
121 STATE ST				
PORTLAND, ME 04101				
		T .		
Location	CBL	Inspection Date		
Location 121 STATE ST	CBL 045 A020001	Inspection Date 2/15/2017		
		-		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 4/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. Rear unit doors	//
NFPA 101- 7.2.1.15.8 FIRE DOOR ASSEMBLY REQ REPAIR; Door openings not in proper operating condition shall be repaired or replaced without delay. Self closers need repair	//
NFPA 101- 7.2.8.6.2 FIRE ESCAPE REQUIRES REPAIR; The authority having jurisdiction shall be permitted to approve any existing fire escape stair that has been shown by load test or other satisfactory evidence to have adequate strength. Treads and railings to be repaired, shored up.	//
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6. Needed in several locations	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements. Smoke alarm in unit 2	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.

Violation		Proposed Date of Completion
wiring installations shall be provided only to temporary wiring installations		//
NFPA 101- 31.3.2.1.1 BOILER PRO 31.3.2.1.1 shall be protected as indi	DTECTION REQUIRED; The areas described in Table icated: Boiler and fuel-fired heater rooms serving more in separation/protection is 1 hour or sprinklers)	//
FINAL DATE OF COMPLETED VI	OLATION(S)	//
FIRE PREVENTION BUREAU RE-	INSPECTION OF COMPLETED VIOLATION(S)	//
questions. VIOLATOR CERTIFICATIO I agree to remedy the violations is understand that I must contact the is entirely within the Bureau's distributed in I further understand that it is my have been remedied to do so. My violations have not been remedie If I fail to comply with this agree	listed within the timeframes provided. If I require addine Fire Prevention Bureau prior to the deadline to requiscretion to grant or deny. To responsibility to schedule a reinspection of my property failure to schedule a reinspection shall be deemed and and add. The ment, I understand that I am liable for penalties pursua	tional time to comply, hest an extension, which ty once the violations admission that the
Portland Code of Ordinances §§ action.	1-15 and 10-25, and 30-A M.R.S. § 4452 and may be s	subject to further legal
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	