

COMMENTS

7/9/94 Window installation not done as submitted,  
trayson placement different, see revised sketches.  
Actually more symmetrical as installed.  
OK.

Cross Reference

Bldg. Permit # 900187

dated 3/21/94.

Inspection Record

Type	Date
Foundation: _____	_____
Framing: _____	_____
Plumbing: _____	_____
Final: _____	_____
Other: _____	_____