September 25, 2015

Vail Properties Llc

23 Pine St

Portland, ME 04102

CBL: 045 E001001

Located at 0118 WINTER ST

NOTICE OF INTENT TO PROSECUTE

Dear Owner/Manager/Occupant,

An inspection of the property located at the address referenced above revealed that the structure and premises fail to comply with NFPA 2009 Fire Code and/or NFPA Life Safety Codes. Attached is a list of those violations.

The above-referenced property is in violation of the Chapter 10, Fire Prevention and Protection, Article 1 of the Portland City Code (the "Code") and National Fire Protection Association (NFPA) 101 Life Safety Code. Please note that the Code is available online at www.portlandmaine.gov.

This is a notice of intent to prosecute. As such, the matter is being referred to the City of Portland Corporation Council for legal action and possible civil penalties as provided for in Chapter 10, Fire Prevention and Protection, 10-25 of the Code and in Title 30- A.M.R.S.A. 4452.

Please be advised that you will need to contact the Fire Prevention Bureau at 207-874-8400 before the court date on the attached Reference to Court letter to either schedule a re-inspection or to submit a plan of action to correct these violations.

Sincerely,

Portland Fire Department

A/C With Startown

Fire Prevention Bureau

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager Vail Properties Llc				Inspector Daniel Dyer		Inspection Date 9/23/2015		
Location CBL 0118 WINTER ST 045 E001001			Status Failed		Inspection Type			
					Fire Company-FP Routine Inspec			
Code		Int/Ext	Floor	Unit No.	Area	Compliance Date		
1) 73.05								
Violation:	NFPA 101- 7.2.1.15.8 FIRE DOOR ASSEMBLY REQ REPAIR; DOOR OPENINGS NOT IN PROPER OPERATING CONDITION SHALL BE REPAIRED OR REPLACED WITHOUT DELAY.							
Notes:	FIRE DOORS REQUIRED							
2) 80.16								
Violation:	NFPA 101-7.9.3 EMERGENCY LIGHTS REQUIRE MAINTENANCE; 7.9.3 Periodic Testing of Emergency Equipment							
	7.9.3.1 Required emergency lighting systems shall be tested in accordance with one of the three options offered by 7.9.3.1.1, 7.9.3.1.2, or 7.9.3.1.3.							
	7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows:							
	(1) Functional testing shall be conducted monthly with a minimum of 3 weeks and a maximum of 5 weeks between tests, for not less than 30 seconds, except as otherwise permitted by 7.9.3.1.1(2).							
	(2) The test interval shall be permitted to be extended beyond 30 days with the approval of the authority having jurisdiction.							
	(3) Functional testing shall be conducted annually for a minimum 1-1/2 hours if the emergency lighting system is battery powered.							
	(4) The emergency lighting equipment shall be fully operational for the duration of the test required by 7.9.3.1.1(1) and (3).							
	(5) Written records of visual inspections and tests shall be kept by the owner for inspection by the authority having jurisdiction.							
Notes:								
3) 80.28								
Violation: Notes:	NFPA 101- 7.5.1.1 EXIT OBSTRUCTED; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. REAR STAIRWELL							

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
Vail Properties Llc		Daniel Dyer	9/23/2015
Location	CBL	Status	Inspection Type
0118 WINTER ST	045 E001001	Failed	Fire Company-FP Routine Inspec

4) 81.10

Violation:

PORTLAND FIRE DEPARTMENT CHAPTER 10 FIRE ALARM INSPECTION STICKER REQUIRED; Provide annual fire alarm inspection sticker at the annunciator. This sticker must be provided by a

licensed master fire alarm company. A list of licensed master fire alarm companies can be found at:

www.portlandmaine.gov/fireprevention.

Notes:

EXPIRED 6/4/2015

5) 55.30

Violation:

NFPA 101-31.2.4.1 TWO EXITS REQUIRED ABOVE FIRST FLOOR; EVERY DWELLING UNIT

SHALL HAVE ACCESS TO NOT LESS THAN TWO SEPARATE EXITS REMOTELY LOCATED

FROM EACH OTHER AS REQUIRED BY 7.5.1.

Notes:

REAR UNITS

Comments:

Inspections from Naviline Fire Inspections. 4 were listed.

DISTRICT COURT Location: Portland Docket No.

CITY OF PORTLAND and body politic and Corporate, located in the County of Cumberland and State of Maine,

Plantiff,

FIRE PREVENTION AND PROTECTION CODE VIOLATION

(M.R. CIV. P. 80H AND 80k)

V.

Vail Properties LLC
Defendant

SUMMONS NUMBER:

354920

This matter has been referred to the Corporation Counsel's Office for immediate legal action with respect to the code violations detailed in the attached letter. It has been assigned the above summons number and will be filed with the Portland District Court and will be assigned for an initial appearance at the Portland District Court 205 Newbury Street Portland, Maine 04101 at 8:30 A.M. on 11/09/2015. I strongly urge you to contact Victoria Meserve at Fire Prevention at (207)-874-8400 or via e-mail at meservev@portlandmaine.gov to set up an inperson meeting to resolve these issues or make alternative arrangements to relieve you of the requirement to appear in Court on 11/09/2015.

Dated: Alar /15

Adam R. Lee, Esq. Bar No. 4143 Associate Corporation Council

City of Portland 389 Congress St Portland, ME 04101 207-874-8480