Approved for Historic Preservation
Certificate of Appropriateness
Date: 11/25/14

South Face of Residence
Closeup of Dormer Joint to be Repaired

South Face of Residence
Closeup of Repairs and Flashing Work to be Done

South Face of Residence
Closeup of Porch Roof Joint Area to be Repaired

East Face (Front) of Residence
Closeup of Bay Window Trim to be Repaired