## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

April 20, 2017

Responsible Party 1:				
SATTIN NEIL E				
PO BOX 8697				
PORTLAND, ME 04104				
Location	CBL	Inspection Date		
<b>Location</b> 147 BRACKETT ST	<b>CBL</b> 045 E029001	Inspection Date 4/3/2017		
		-		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 5/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 80- ANNEX D.4 1-HOUR FIRE DOORS ASSEMBLIES REQ; Listings are provided for floor fire door assemblies that are installed in fire-rated floor-ceiling or roof-ceiling assemblies that have been tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, .75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door openings permitted for each 100 square feet of floor or ceiling.	
Door to basement enters to and from the rear common egress staircase. This door is required to be fire rated.	
NFPA 70- ARTICLE 590.6 EXT. CORD USED FOR PERMENANT WIRING; Ground-fault protection for personnel for all TEMPORARY wiring installations shall be provided to comply with 590.6 (A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment or similar activities. Lighting in basement utilizing extension cords for operation.	
NFPA 70 LABEL ALL ELECTRICAL PANELS; Refer to NFPA 70 for requirements regarding labeling of all electrical panels.	
NFPA 101- 7.1.10.2.1 DEBRIS INSIDE BUILDING; No furnishings, decorations, or other objects shall obstruct exits or their access there to, egress therefrom, or visibility thereof. Basement needs cleaning.	

Violation		Proposed Date of Completion
NFPA 1 EXCESSIVE/DISORDE	RLY STORAGE; Reference NFPA 1 for excessive fuel-load.	/ /
Basement		//
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	to reject or modify any proposed plan of action, and may cal capacity to complete the proposed plan. Please contaction.	
	ns listed within the timeframes provided. If I require add t the Fire Prevention Bureau <u>prior to the deadline</u> to requ s discretion to grant or deny.	
v	my responsibility to schedule a reinspection of my proper My failure to schedule a reinspection shall be deemed an died.	•
	reement, I understand that I am liable for penalties pursu §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	