
CONSULTANTS:

REVISIONS:

CONDITIONS PHOTOGRAPHS





FRONT FACADE FROM BRACKETT STREET




FRONT FACADE FROM BRACKETT STREET




MAIN ENTRANCE & RAMP




WEST FACADE OF WOOD-CLAD BUILDING




MANSARD ROOF & THIRD FLOOR WINDOWS




MANSARD ROOF & THIRD FLOOR WINDOWS




MANSARD ROOF & THIRD FLOOR WINDOWS



MANSARD ROOF & CORNICE DETAIL AT CORNER




SECOND FLOOR ARCHED WINDOW



SECOND FLOOR ARCHED WINDOWS SOUTH ELEVATION



FRONT FACADE AT STREET LEVEL



DOOR IN SOUTH FACADE OF 2-STORY BRICK BUILDING