

PINKHAM ENVIRONMENTAL, INC.

P.O. Box 405 Boothbay, MAINE
(207) 837-0571

October 4, 2013

Mike Lemar
New Meadows Abatement
P.O. Box 227
Bath, Maine 04530

Re: 183 Brackett Street-Portland, ME- Visual Evaluation & PCM Clearance-PEI # 13-1237

Mike:

Please find attached the project report for the asbestos abatement activities conducted at 137 Brackett Street in Portland, Maine.


On August 19, 2013 Pinkham Environmental Inc. performed a visual evaluation and PCM air-clearance sampling after the removal of 300 square feet of floor tiles and 24 square feet of boiler isolation. The removal took place on the 1st floor & basement. The final visual evaluations and PCM air-clearance sampling were conducted in accordance with the State of Maine Department of Environmental Protection's Asbestos Management Regulations Chapter 425, section 8.

The Pinkham Environmental representative has determined that the airborne fiber concentration was below the Environmental Protection Agency recommended safe level for re-occupancy of 0.01 f/cc.

The project report includes the Daily Field Report, PCM Analytical Data, Final Visual Evaluation Checklist, and Certificate of Re-occupancy for your records.

Should you have any further questions, please contact us at (207) 837-0571.

Sincerely,
Pinkham Environmental Inc.
Kim Pinkham



Air Monitor (MDEP #AM -0324)

**PINKHAM ENVIRONMENTAL INC.
P.O. BOX 405
BOOTHBAY, MAINE 04537**

CERTIFICATE OF RE-OCCUPANCY

CLIENT: NEW MEADOWS ABATEMENT
PROJECT: 183 Bracket Street
PEI #: 13-1237
BUILDING: RESIDENTIAL
WORK AREA: 1st Floor-Basement

The airborne fiber concentration in the work area has been determined to be below the Environmental Protection Agency's recommended safe level for re-occupancy of 0.01 f/cc. The Pinkham Environmental representative has declared this area available for re-occupancy by unprotected personnel on the 19th day of August 2013 at 1530 hours.



[field technician signature]
PINKHAM ENVIRONMENTAL INC.

Date: 8/19/13

Pinkham Environmental, Inc.
P.O. Box 405
Boothbay, Maine 04537

Final Visual Evaluation Checklist

PROJECT NAME:	183 Brackett Street	AIR MONITOR: (initials & AM#)	KWP AM #0324
PEI PROJECT #:	13-1237	ASBESTOS CONTRACTOR:	New Meadows Abatement
BUILDING:	Residential	DATE:	8/19/2013
LOCATION:	1st Floor & Basement	TIME COMPLETED:	1230

		<i>Final Air Sample Results</i>		
	<input checked="" type="checkbox"/>	Sample #	Results	Date
Floors	<input checked="" type="checkbox"/>			
Pipes	<input type="checkbox"/>			
Ventilation Ducts	<input type="checkbox"/>	1237-1	0.003	8/19/2013
Hangers, structural, equipment, uni-struts, etc.	<input checked="" type="checkbox"/>	1237-2	0.002	
Joints, couplings, elbows	<input type="checkbox"/>	1237-3	0.003	
Mechanical equipment	<input type="checkbox"/>	1237-4	blank	
Contractor equipment	<input checked="" type="checkbox"/>			
Other (list): SURFACES	<input checked="" type="checkbox"/>			
		Date:	8/19/2013	
		<i>Pinkham Environmental, Inc.</i>		
		<i>Laboratory</i>		

Areas inspected for residual dust

All visible suspect debris removed		1st Attempt	
Final HEPA vacuuming/wet wiping	<input checked="" type="checkbox"/>	2nd Attempt	<input checked="" type="checkbox"/>
All water collected, filtered, disposed of	<input checked="" type="checkbox"/>	3rd Attempt	<input type="checkbox"/>
Primary layer of containment removed	<input checked="" type="checkbox"/>	Pass	<input type="checkbox"/>
All equipment cleaned or bagged	<input checked="" type="checkbox"/>	Fail	<input type="checkbox"/>
	<input type="checkbox"/>		<input type="checkbox"/>