

Primary Structural System: BALLOON FRAME

Chimney Placement: INTERIOR END

Roof Configuration: GABLE SIDE

Roof Material: ASPHALT

Exterior Wall Materials: ASBESTOS

Foundation Material: BRICK

Outbuildings/Features:

HISTORICAL DATA

Documentated Date of Construction:

Estimate Date of Construction: c. 1840

Date Major Additions/Alterations:

Architect:

Contractor: William Kilby

Original Owner: William Kilby

Subsequent Signific. Owner:

Dates:

Cultural/Ethnic Affiliation:

Historic Context(s): HABITATION

Comments:

1924 Tax Assessor's Report; 1972 Survey Form

Historical Drawings Exist N

Location:

ENVIRONMENTAL DATA

Site Integrity: Original Y Moved N Date Moved