

Property Address: 197 Spring Street

Portland Historic Resources Inventory

Inventory #: SP-226

Assessor's C/B/L: 45-E-21

District: Spring Street

Map #: 226

Rating:

Local Code: CONTRIBUTING

National Register: Ind. Listing N/A

District Spring Street

Date of Placement: Local 08/01/1990 National 04/03/1970

Description of Significant Features and Subsequent Alterations:

The addition of asbestos siding has greatly altered the detailing of this Greek Revival dwelling, for the cornerboards, frieze, and raking cornice are no longer visible. The entrance is on the western elevation in the rear bay. Originally a full-width porch with indented paneled porch supports led up to the door, now it is only a hood supported by simple posts. The wooden steps have been replaced with cement steps. A fire escape leads from the western gable window to the porch hood. The roof is punctuated by two tall interior end wall chimneys and two enclosed gabled dormers with coupled windows. An ell extends out to the rear and on the eastern elevation there is a large ground floor bay window. There are painted stone lintels over the 4 foundation windows. The dormers are additions as is the fire escape, asbestos siding, and altered window sash (from 6/6 to 1/1). Despite exterior alterations, this dwelling is representative of the 1830s and 40s development of Spring Street. It is stylistically similar to 205 Spring Street which is in a restored state and shows what this building would look like without the dormers and with a full width side porch.

City Review of Certificates:

Date	Action	Type	Summary of Work
------	--------	------	-----------------

Property Name: William Kilby House

Property Name (Other):

Street Address: 197 Spring Street

Town: Portland

County: Cumberland

Date Surveyed: 06/1990

Surveyor: Rick Redlon

Updated:

(date) by (Surveyor)

by

Owner Name: Larry and Joanne Gaudet
Owner Address:

Primary Use (Present): MULTI FAMILY

Condition: FAIR

ARCHITECTURAL DATA

Primary Stylistic Category: GREEK REVIVAL

Other Stylistic Category: ITALIANATE

Height: 2 1/2 STORY

Primary Façade Width (Main Block, Use Ground Floor): 4 Bay

Appendages: REAR ELL DORMERS PORCH

Porch: ATTACHED ONE STORY LESS FULL WIDTH

Plan: BACK HALL

Primary Structural System:

BALLOON FRAME

Chimney Placement: INTERIOR END

Roof Configuration: GABLE SIDE

Roof Material: ASPHALT

Exterior Wall Materials: ASBESTOS

Foundation Material: BRICK

Outbuildings/Features:

HISTORICAL DATA

Documented Date of Construction:

Estimate Date of Construction: c. 1840

Date Major Additions/Alterations:

Architect:

Contractor: William Kilby

Original Owner: William Kilby

Subsequent Signific. Owners:

Dates:

Cultural/Ethnic Affiliation:

Historic Context(s): HABITATION

Comments:

1924 Tax Assessor's Report; 1972 Survey Form

Historical Drawings Exist: N

Location:

ENVIRONMENTAL DATA

Site Integrity: Original Y Moved N Date Moved


三

Use of Bldg.	Office	Lot	1
Tenants and Rooms	None	Name	
Rentals	\$150 per month	Per	1/3
Age	Old		
Condition of Repair		Fair	

Land - 5675 Corner - Interior - Alley
Front - Depth - ft.

COMPIRATION

Area	Multipplier	Coefficient
5675	94	5334
Year	Unit3	Coefficient
19	35	5334



Survived by *John E. Clegg*
APR 1 1924
(Remarks on other side)

1990 SURVEY, PHOTO

