

Code **Int/Ext**
Status/Date **Notes:** **Unit No.** **Floor** **Area** **Compliant/Compliance Date**

ScheduleID: **ViolationID:**

6-108.1	Exterior				<input type="checkbox"/>		Violation Date
Open	repair unattached gutters						<input type="text" value="12/13/2006"/>
6-108.1	Exterior				<input type="checkbox"/>		Violation Date
Open	replace decayed fascia board(s)						<input type="text" value="12/13/2006"/>
6-108.1	Exterior			Various locations	<input type="checkbox"/>		Violation Date
Open	replace broken and decayed clapboards						<input type="text" value="12/13/2006"/>
6-109.1	Interior				<input type="checkbox"/>		Violation Date
Open	Basement area must be cleaned						<input type="text" value="12/13/2006"/>
6-109.2	Exterior				<input type="checkbox"/>		Violation Date
Open	Trash must be removed from back yard area						<input type="text" value="12/13/2006"/>
6-116.3	Interior				<input type="checkbox"/>		Violation Date
Open	stairway area in front entrance must be cleared.						<input type="text" value="12/13/2006"/>
6-108.4	Interior	1			<input type="checkbox"/>		Violation Date
Open	unit one inside railings and ballusters must be repaired						<input type="text" value="12/13/2006"/>
6-108.4	Exterior				<input type="checkbox"/>		Violation Date
Open	Front entrance railing must be repaired						<input type="text" value="12/13/2006"/>
6-108.3	Interior				<input type="checkbox"/>		Violation Date
Open	broken window in French Door must be replaced						<input type="text" value="12/13/2006"/>
6-108.1	Exterior			Various locations	<input type="checkbox"/>		Violation Date
Open	Peeling and Missing Paint various locations exterior of building						<input type="text" value="12/13/2006"/>