

THIS IS NOT A BOUNDARY SURVEY.

THIS IS THE RESULT OF TAPE MEASUREMENT, NOT THE RESULT OF AN INSTRUMENT SURVEY AND IS CERTIFIED TO THE TITLE INSURANCE COMPANY AND ABOVE LISTED ATTORNEY AND LENDER.

THERE ARE NO DEEDED EASEMENTS IN THE ABOVE REFERENCED DEED OR ENCROACHMENTS WITH RESPECT TO BUILDINGS SITUATED ON THIS LOT EXCEPT AS SHOWN.


THE LOCATION OF THE DWELLING SHOWN DOES NOT FALL WITHIN A SPECIAL FLOOD HAZARD ZONE,

THE LOCATION OF THE DWELLING AS SHOWN HEREON WAS IN COMPLIANCE WITH THE LOCAL ZONING LAWS IN EFFECT WHEN CONSTRUCTED (WITH RESPECT TO STRUCTURAL SETBACK REQUIREMENTS ONLY).

PARCEL NUMBERS FROM ASSESSOR'S MAP.

SURVEYING ENGINEERING LAND PLANNING Northeast Civil Solutions

INCORPORATED 153 US ROUTE 1, SCARBOROUGH, MAINE 04074







GENERAL NOTES: (1) The declaration made above are on the basis of my knowledge, information, and belief as the result of a mortgage inspection tape survey made to the normal standard of care of professional land surveyors practicing in Maine. (2) Declarations are made to the above named client only as of this date. (3) This plan was not made for recording purposes, for use in preparing deed descriptions or for constructions. (4) Verifications of property line dimensions, building offsets, fences, or lot configuration may be accomplished only by an accurate instrument survey.