Portland, Maine



Yes. Life's good here.

Danielle P. West-Chuhta Corporation Counsel

Michael I. Goldman Associate Counsel Anne M. Torregrossa Associate Counsel Victoria E. Morales Associate Counsel

December 15, 2016

NOTICE OF INTENT TO PROSECUTE

To Whom it May Concern,

Please see the attached Notice of Violation and Order to Correct from the City of Portland Fire Prevention Bureau. The Fire Prevention Bureau has referred this matter to me for prosecution in the event that you do not complete and return the required plan of action by the date contained in the Notice of Violation. Your failure to comply will result in the issuance of a summons for you to appear in court, and the imposition of civil penalties in the minimum amount of \$100 per violation per day.

Please contact the Fire Prevention Bureau at (207)874-8400 to resolve these outstanding violations. I look forward to your anticipated cooperation and appreciate your efforts to help keep the citizens of Portland safe.

Sincerely,

Anne M. Torregrossa

Associate Corporation Counsel

hme Tonequoso

City of Portland

CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

December 15, 2016

Responsible Party 1:				
HAROLD E STERNBURG FAMILY TRUST				
657 CONGRESS ST 1ST FLOOR				
PORTLAND, ME 04101				
Location	CBL	Inspection Date		
546 CUMBERLAND AVE	047 A007001	12/6/2016		
Inspector	Inspection Type	Status		
Daniel Dyer	FP Routine Inspection	Failed		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 12/30/2016. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED, OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF OTHER LEGAL REMEDIES.

Violation	Proposed Date of Completion
NFPA 101-7.9.3 EMERGENCY LIGHTS REQUIRE MAINTENANCE; 7.9.3 Periodic Testing of Emergency Equipment 7.9.3.1 Required emergency lighting systems shall be tested in accordance with one of the three options offered by 7.9.3.1.1, 7.9.3.1.2, or 7.9.3.1.3. 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted monthly with a minimum of 3 weeks and a maximum of 5 weeks between tests, for not less than 30 seconds, except as otherwise permitted by 7.9.3.1.1(2). (2) The test interval shall be permitted to be extended beyond 30 days with the approval of the authority having jurisdiction. (3) Functional testing shall be conducted annually for a minimum 1-1/2 hours if the emergency lighting system is battery powered. (4) The emergency lighting equipment shall be fully operational for the duration of the test required by 7.9.3.1.1(1) and (3). (5) Written records of visual inspections and tests shall be kept by the owner for inspection by the authority having jurisdiction. 2nd and 3rd floor rear	//
NFPA 101- 7.5.1.1 EXIT OBSTRUCTED ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. 3rd floor. And rear of apt 6	IMMEDIATELY remove all obstructions from the exits. Your signature below indicates that all obstructions have been removed and will not be replaced.

Violation		Proposed Date of Completion
through out with an existing, complete aut be installed in accordance with 9.6.2.10, a	REQUIRED; In buildings other than those equipped comatic smoke detection system, smoke alarms shall as modified by 31.3.4.5.2, outside every sleeping coms and on all levels of the dwelling unit, including	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 1 EXCESSIVE/DISORDERLY STO	DRAGE ; Reference NFPA 1 for excessive fuel-load.	//
Rubbish in basement		, , ,
FIRED GRILL, CHARCOAL GRILL, OR C	II OR GRILL ON BALCONY; NO HIBACHI, GAS- OTHER SIMILAR DEVICES USED FOR COOKING, L BE USED OR KINDLED ON ANY BALCONY OR WITHIN 10 FTOF ANY STRUCTURE	//
NFPA 101- 8.3.4.2 60 MINUTE FIRE DOO that states fire door assemblies for vertica chutes) are rated and required for 1 hour. From units into hallways	//	
VIOLATOR CERTIFICATION		
	within the timeframes provided. If I require addi Prevention Bureau <u>prior to the deadline</u> to reque to grant or deny.	
· ·	onsibility to schedule a reinspection of my proper are to schedule a reinspection shall be deemed an	<u> </u>
	I understand that I am liable for penalties pursua and 10-25, and 30-A M.R.S. § 4452 and may be s	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		

Fire Prevention Bureau

Date