

536 WILBERLAND AVENUE



SHAY-KRITZER

Full cut - 920R - Half cut - 9212R - 1/2 cut - 9213R - 3/4 cut - 9214R

CITY OF PORTLAND, MAINE

Department of Building Inspection

534-536 Cumberland Avenue

July 11, 1973

C
O
P
Y

Susanne & Robert T. Willard
207 High Street

Dear Mr. & Mrs. Willard:

It has come to the attention of this department that a second floor stairway has been installed without a permit at the above named location. It is required that you bring to this office a floor plan showing the location of the stairway and apply for a permit. At 536 Cumberland Avenue you have a third floor apartment with only one means of egress. A second means of egress is required by law.

It will be necessary for you to bring plans of the apartment to this office and talk with Mr. Soule regarding both situations.

It is required that you apply within ten days, not later than July 25th so that further action by this department will not become necessary.

Very truly yours,

Hugh Irving
Building Inspector

HI:m



CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION
COMPLAINT

Location: 536 Cumberland Ave.

INSPECTION COPY

COMPLAINT NO. 73/29

Date Received April 2, 1973


Location 536 Cumberland Ave. Use of Building _____
 Owner's name and address Robert G. Siquarone, Willard Telephone _____
~~Owner's name and address~~ 207 Fifth St Telephone _____
 Complainant's name and address Fire Dept. Telephone _____

Description:

Third floor - one way out - needs second means of egress

NOTES: 7/17/73. This complaint keeps returning
to my desk with no explanation of
it. I have had a letter written on it
& mailed by Tel. to the owner of it
letters in your mailbox.
Ref: 534 also -

Letter Huj:



534-536 Cumberland Avenue

July 11, 1973

Susanne & Robert T. Willard
207 High Street

Dear Mr. & Mrs. Willard:

It has come to the attention of this department that a second floor stairway has been installed without a permit at the above named location. It is required that you bring to this office a floor plan showing the location of the stairway and apply for a permit. At 536 Cumberland Avenue you have a third floor apartment with only one means of egress. A second means of egress is required by law.

It will be necessary for you to bring plans of the apartment to this office and talk with Mr. Soule regarding both situations.

It is required that you apply within ten days, not later than July 25th so that further action by this department will not become necessary.

Very truly yours,

Hugh Irving
Building Inspector

HI:m

CITY OF PORTLAND, MAINE
Application for Permit to Install Wires

Permit No. 54779

Issued

Portland, Maine April 21, 1964

To the City Electrician, Portland, Maine:

The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

(This form must be completely filled out — Minimum Fee, \$1.00)

Owner's Name and Address Amy Bishop Tel. _____
 Contracto.'s Name and Address Sanborn Electric Tel. 72-46582
 Location 534 Cumberland of Building Residence
 Number of Families 1 Apartments _____ Stores _____ Number of Stories _____
 Description of Wiring: New Work _____ Additions _____ Alterations _____
100 A. & Range
 Pipe _____ Cable _____ Metal Molding _____ BX Cable _____ Plug Molding (No. of feet) _____
 No. Light Outlets _____ Plugs _____ Light Circuits _____ Plug Circuits _____
 FIXTURES: No. _____ Light Switches _____ Fluor. or Strip Lighting (No. feet) _____
 SERVICE: Pipe _____ Cable _____ Underground _____ No. of Wires _____ Size _____
 METERS: Relocated _____ Added _____ Total No. Meters _____
 MOTORS: Number _____ Phase _____ H. P. _____ Amps _____ Volts _____ Starter _____
 HEATING UNITS: Domestic (Oil) _____ No. Motors _____ Phase _____ H.P. _____
 Commercial (Oil) _____ No. Motors _____ Phase _____ H.P. _____
 Electric Heat (No. of Rooms) _____
 APPLIANCES: No. Ranges Watts _____ Brand Feeds (Size and No.) _____
 Elec. Heaters _____ Watts _____
 Miscellaneous _____ Watts _____ Extra Cabinets or Panels _____
 Transformers _____ Air Conditioners (No. Units) _____ Signs (No. Units) _____
 Will commence _____ 19 _____ Ready to cover in _____ 19 _____ Inspection _____ 19 _____
 Amount of Fee \$ 3.50

Signed Sanborn Electric

DO NOT WRITE BELOW THIS LINE

SERVICE METER _____ GROUND _____
 VISITS: 1 4/22/66 2 _____ 3 _____ 4 _____ 5 _____ 6 _____
 7 _____ 8 _____ 9 _____ 10 _____ 11 _____ 12 _____

REMARKS:

INSPECTED BY J. G. Herbert
 (OVER)

LOCATION *534 Cumberland Exp*
 INSPECTION DATE *4/22/66*
 WORK COMPLETED *4/22/66*
 TOTAL NO. INSPECTIONS *1*
 REMARKS:

FEES FOR WIRING PERMITS EFFECTIVE JULY 31, 1963

WIRING		
1 to 30 Outlets	(including switches)	\$ 2.00
31 to 60 Outlets	(including switches)	3.00
Over 60 Outlets, each Outlet	(including switches)	.05
(Each twelve feet or fraction thereof of fluorescent lighting or any type of plug molding will be classed as one outlet).		
SERVICES		
Single Phase		2.00
Three Phase		4.00
MOTORS		
Not exceeding 50 H.P.		3.00
Over 50 H.P.		4.00
HEATING UNITS		
Domestic (Oil)		2.00
Commercial (Oil)		4.00
Electric Heat (Each Room)		.75
APPLIANCES		
Ranges, Cooking Tops, Ovens, Water Heaters, Disposals, Dish-washers, etc. -- Each Unit		1.50
TEMPORARY WORK (Limited to 6 months from date of permit)		
Service, Single Phase		1.00
Service, Three Phase		2.00
Wiring, 1-50 Outlets		1.00
Wiring, additional outlet over 50		.02



(A) APARTMENT HOUSE ZONE
APPLICATION FOR PERMIT

Class of Building or Type of Structure Brick Building
Portland, Maine, June 25, 1952

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect ~~alter or improve~~ install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 536 Cumberland Avenue Within Fire Limits? _____ Dist. No. _____
Owner's name and address Joseph P. & Agnes L. Murphy, 536 Cumberland Ave. Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address OWNER Telephone _____
Architect _____ Specifications _____ Plans yes No. of sheets 2
Proposed use of building Lodging house No. families _____
Last use _____ " " _____ No. families _____
Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____
Other buildings on same lot _____
Estimated cost \$ 250.00 Fee \$ 2.00

General Description of New Work

To construct outside wooden fire escape on rear of building from
third floor to ground as per plan

7/29/52 - Returned of plan to Mrs. Murphy

Chief's order 7/1/52
and one of required from 3rd floor + afa required

CERTIFICATE OF OCCUPANCY - E
REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO owners

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

[Signature]
Inspector of Buildings

INSPECTION COPY

Signature of owner

Agnes L. Murphy

AP 536 Cumberland Ave.

June 30, 1952

Mr. Joseph W. Murphy,
536 Cumberland Avenue
Portland, Maine

Copy to the Fire Dept.

Dear Mr. Murphy:

Your plan of proposed wooden outside stairway for fire escape at 536 Cumberland Avenue is not complete enough to show compliance with Building Code requirements--no sizes and spacing of members in stairway or platform, no masonry pier foundations beneath posts and bottom of stairs, extending 4' below the grade and 6" above, no width of treads, etc. We need complete details of this new construction by way of a blueprint with all of the information on it printed from the original--so that the records may show that you have a copy of the same information you have given us.

If the window to lead to the fire escape is to be double hung, it is not high enough since an opening no less than 28" high is required for exit when the bottom sash is way up. If approved by the Fire Department, however, the window could be made a casement sash and the total opening would be large enough. The landing of the fire escape is shown 20" below the window sill while 18" is the maximum permitted by the Code. In event you should decide to put in a door instead of a casement or a larger double hung window, the opening must be no less than 30" wide and 6 1/4" high and the threshold of the door must be no more than 12" above the stair platform. The platform is required to be wide enough so that there will be at least 9" on each side between the window or door jamb and the landing.

However, of first importance is the fact that the proposed stairway would be an unlawful encroachment upon the required rear yard. It appears that the rear wall of your building is about 21' from your rear property line. The depth of rear yard between the rear wall of the building and rear line is required by the Zoning Ordinance in the Apartment House Zone where the property is located to be 25% of the depth of the lot (the latter appears to be 95.84' which figures out a rear yard depth of about 24'). The plan shows the platform and stairway to project from the rear wall about 21', so there is that such encroachment which we have no authority to issue a permit to allow. It may be that our figures are somewhat in error because you furnished no plat plan, but it hardly seems that we can be far enough off to make the stairway in conformity with the Zoning Ordinance.

You have appeal rights under the Zoning Ordinance, to the Fire Chief for his consideration to make sure satisfactory to him, if you should desire to rescind or are inclined to grant such appeals when there conform with Fire Department orders.

Send your plan
to the Board of Appeals
by way of complying

If you decide to file an appeal, please give us a correct plat plan and notify us of your desire, whereupon you will be sent a certification letter.

If you propose the concrete steps shown on your plan are already in place. If they are proposed new, we shall need details of them also, including foundations 4' below the surface of the ground.

June 30, 1952

Mr. Joseph F. Murphree---2

Inasmuch as the records show that the Fire Department order is more than five years old, I presume they are requiring you to proceed quickly. If you desire an appeal it would be well to file the information and get the appeal filed quickly so that you may get consideration of the Board of Appeals at the earliest possible date.

Very truly yours,

Warren McDonald
Inspector of Buildings

WMC/D/H

CITY OF PORTLAND, MAINE
Department of Building Inspection

(date) June 30, 1952

To: Oliver T. Sanborn
Chief of the Fire Department

Location: 536 Cumberland Ave.

From: Warren McDonald
Insptr. of Bldgs.

Subject: Application for permit for
improvements at above location,
required by order of Chief of Fire
Department dated March 11, 1947

While our two departments have done a good job of coordination under the Safety Ordinance--yours issuing the orders after inspection and ours issuing permits for improvements to be made,--

The confusion on the part of many people, who come in here, as to who has ordered them to do what,

The fact that on some jobs a permit has been issued, and the work done, only to have your inspector find that the situation did not then satisfy your order under the law,

And, the fact that you are permitted under the Building Code to exercise discretion as to details of means of egress in an existing building where there is no substantial increase in number of persons accommodated, while we must proceed under the precise terms of the Code unless deviation in this connection is approved by yourself--

leads me to the belief that each situation ought to be checked before any permits are issued, presumably by the inspector in your department who made the inspection on which the original order was based, to see:

1. If the work contemplated will completely satisfy the order.

2. To see, if possible, whether or not there may be some more economical way of satisfying the order, and, if so, to recommend that way to the owner.

To that end there is attached for your consideration applications for permits at the above location.

Remarks relating to this particular job:

The proposed wooden fire escape represents an unlawful encroachment of the rear yard under the Zoning Ordinance, but before suggesting an appeal to the owner it seems best to make sure that you approve the proposed means of egress.

Warren McDonald
Inspector of Buildings

Found single hung
window or door on
3rd floor leading to
escape.

R.H.F. 7/1/52
Capt.

Memorandum from Department of Building Inspection, Portland, Maine

536 Cumberland Avenue--Construction of outside wooden fire escape for Mrs. Agnes L. Murphy by owner.

To the Fire Dept:

July 29, 1952

Mrs. Murphy came into the office today and said she isn't going ahead with the fire escape. She says she will not let any rooms at all.

We are notifying you to this effect so that you can do whatever you think best.

PH

(Signed) Warren McDonald
Inspector of Buildings



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine,

PERMIT 155030
01745
JUL 23 1947

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 536 Cumberland Ave Use of Building Sewelling No. Stories 2 New Building Existing " "
Name and address of owner of appliance Frank L. Murphy 536 Cumberland Ave.
Installer's name and address Ballard Oil & Equip. 135 Marginal Way Telephone 2-1941

General Description of Work

To install one fully automatic oil burner for heating steam heat

IF HEATER, OR POWER BOILER

Location of appliance or source of heat Type of floor beneath appliance
If wood, how protected? Kind of fuel
Minimum distance to wood or combustible material, from top of appliance or casing top of furnace
From top of smoke pipe From front of appliance From sides or back of appliance
Size of chimney flue Other connections to same flue
If gas fired, how vented? Rated maximum demand per hour

IF OIL BURNER

Name and type of burner 1 - Eco - CCS Labelled by underwriter's laboratories? yes
Will operator be always in attendance? No Does oil supply line feed from top or bottom of tank? bottom
Type of floor beneath burner Cement
Location of oil storage basement Number and capacity of tanks 1 - 275 gallon
If two 275-gallon tanks, will three-way valve be provided?
Will all tanks be more than five feet from any flame? yes How many tanks fire proofed? none
Total capacity of any existing storage tanks for furnace burners none

IF COOKING APPLIANCE

Location of appliance Kind of fuel Type of floor beneath appliance
If wood, how protected?
Minimum distance to wood or combustible material from top of appliance
From front of appliance From sides and back From top of smokepipe
Size of chimney flue Other connections to same flue
Is hood to be provided? If so, how vented?
If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:

OK 7-22-47 [Signature]

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

INSPECTION COPY

Signature of Installer

[Signature: Ballard Oil & Equip. A. J. Burns]

Permit No. 47/1745
Location 536 Cumberland Ave
Owner Frank B. Murphy
Date of permit 7/23/47
Approved [Signature]

NOTES

- 1. Fill Pipe
- 2. Vent Line
- 3. King of vent
- 4. Burner Rigidity & Supports
- 5. Name & Label
- 6. Stack Control
- 7. High Limit Control
- 8. Remote Control
- 9. Piping supports & Protection
- 10. Valves in Service Line
- 11. Capacity of Tanks
- 12. Tank Rigidities & Supports
- 13. Tank Distances
- 14. Oil Drainage
- 15. Instruction Chart
- 16.



(A) APARTMENT HOUSE ZONE
 CITY OF PORTLAND, MAINE
 DEPARTMENT OF BUILDING INSPECTION

Complaint No. C-17-26

COMPLAINT

INSPECTION COPY

Date received March 26, 1943

Location 536 Cumberland Avenue Use of Building _____

Owner's name and address Portland Savings Bank 121 Congress St. Telephone _____

Tenant's name and address J. Frank Murphy (reported as owner) Telephone _____

Complainant's name and address McD. Telephone _____

Description: Question of legal use of the building as a lodging house. See application for building permit dated 3/10/43 which indicates four lodging rooms.

INSPECTION NOT COMPLETED

Handwritten:
 2-31-43

(A) APARTMENT HOUSE ZONE

Complaint No. C-43-56

Location 536 Cranberryland Ave

Date Received 3/26/43.

Date Disposed of

NOTES

3/26/43 Letter writ

SURVEY AND INVESTIGATION OF TENEMENT AND LODGING HOUSES
QUESTIONABLE AS TO LEGAL AND SAFE USE

1. Location CUMBERLAND AVE. 536 Date investigation commenced _____
2. References: Complaints C-43-26 ^{P.B.A.} Inq. _____
3. Present Owner and Address _____ MURPHY - 536 Cumberland Ave.
4. Present Lessee and Address _____
5. Building Permit Record: 3/2/1160 8/11/132 1700F 1/2

Assessors' Record

6. Survey 1924: Owner _____ : No. tenants _____
No. rooms _____; Class of Use Single
7. Assessors' change record since 1924 1932 COVER ONE side of lot.

8. Change of Owners, 1924 to date 1925 Josephine G. McFaul, Jos. Line G. Deys McFaul
1929 Gilbert M. Cortwell, 1933 PORTLAND Savings BANK.

9. City Directory Record

1926 <u>James A. McFaul</u>	1936 <u>Mrs. Nellie Harding</u>
1927 <u>MINNIE L. O'CONNOR</u>	1937 <u>Same</u>
1928 <u>VACANT</u>	1938 <u>Mrs. Nellie Harding - 2-3663</u>
1929 <u>VACANT</u>	1939 <u>Mrs. Agnes HANNIGAN</u>
1930 <u>Mrs. Harriet T. HUMPHREY</u>	1940 <u>Mrs. Violet L. OWENS</u>
1931 <u>ARTHUR E. PATTERSON (Edith)</u>	1941 <u>J. Frank Murphy (AGNES L.)</u>
1932 <u>VACANT</u>	1942 <u>Same (AGNES L.)</u>
1933 <u>Joseph H. RYAN</u>	1943 <u>Same</u>
1934 <u>VACANT</u>	1944 _____
1935 <u>VACANT</u>	1945 _____

10. Miscellaneous

Conclusions and Action

Rept. 2366D-I

March 26, 1943

Mr. J. Frank Murphy,
538 Cumberland Avenue,
Portland, Maine

Subject: Application for building permit
to cover finishing off 3rd floor room at
538 Cumberland Avenue

Dear Sir:

As I explained to Mrs. Murphy over the telephone there is a question which we have not had time to determine as to whether or not your building is being used legally as a lodging house. I understand that you do have a rooming house license from the State Health Department, but I am referring to the legal use of the building under the city building law.

It is clear, however, that I am unable to issue this permit for finishing off the extra room on the third floor because there is only one exit from that floor. If you can find a way and see fit to attempt to provide a second exit from the third floor, then it would be well to make a plan of it and file the plan with this application for a permit and include the proposed work of the inside stairway or outside fire escape in the same application, increasing the estimated cost of the work accordingly.

The provision of this extra room raises some important questions as to safety, and besides the extra exit you might be confronted with requirements for extra fire protection such as fire resistive partitions and a fire door around the cellar stairs, depending largely upon just how you planned ultimately to use the third floor rooms.

If you decide to give up finishing off the third floor rooms, and will return the receipt for the fee paid to this office, your money will be refunded by voucher.

Very truly yours,

WMcD/H

Inspector of Buildings

536. Campbell & Co
Hold. See letter
~~Amos~~
3/26/43

Rept. 29360-I

March 26, 1943

Mr. J. Frank Murphy,
536 Cumberland Avenue,
Portland, Maine

Subject: Application for building permit
to cover finishing off 3rd floor room at
536 Cumberland Avenue

Dear Sir:

As I explained to Mrs. Murphy over the telephone there is a question which we have not had time to determine as to whether or not your building is being used legally as a lodging house. I understand that you do have a rooming house license from the State Health Department, but I am referring to the legal use of the building under the city building law.

It is clear, however, that I am unable to issue this permit for finishing off the extra room on the third floor because there is only one exit from that floor. If you can find a way and see fit to attempt to provide a second exit from the third floor, then it would be well to make a plan of it and file the plan with this application for a permit and include the proposed work of the inside stairway or outside fire escape in the same application, increasing the estimated cost of the work accordingly.

The provision of this extra room raises some important questions as to safety, and besides the extra exit you might be confronted with requirements for extra fire protection such as fire resistive partitions and a fire door around the cellar stairs, depending largely upon just how you planned ultimately to use the third floor rooms.

If you decide to give up finishing off the third floor rooms, and will return the receipt for the fee paid to this office, your money will be refunded by voucher.

Very truly yours,

W McD/H

Inspector of Buildings

agf
1/26/43
JFM



APARTMENT HOUSE ZONING
APPLICATION FOR PERMIT

Class of Building or Type of Structure Second Class Permit No. _____

Portland, Maine, March 10, 1913

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect ~~also work on~~ the following building ~~structure~~ ~~equipment~~ in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 526 Cumberland Avenue Within Fire Limits? YES Dist. No. 1
Owner's or Lessee's name and address J. F. Murphy, 526 Cumberland Ave. Telephone 2-7604
Contractor's name and address Oxley Telephone _____
Architect _____ Plans filed _____ No. of sheets _____
Proposed use of building dwelling house (1 lodging room) No. families 1
Other buildings on same lot _____
Estimated cost \$ 125. Fee \$ 1.00

Description of Present Building to be Altered

Material brick No. stories 3 Heat steam Style of roof pitch Roofing asphalt
Last use dwelling house (1 lodging room) No. families 1

General Description of New Work

To finish off ~~with~~ ~~existing~~ room on third floor app. 11' x 12' - 2x4 studs 16" OC
pressed board, for use by member of owner's family
existing floor joists 2x8, 16" OC - height of room 7' 6"

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Is any plumbing work involved in this work? _____
Is any electrical work involved in this work? _____ Height average grade to top of plate _____
Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
To be erected on solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____
Kind of heat _____ Type of fuel _____ Is gas fitting involved? _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Material columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____ to be accommodated _____
Total number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? NO
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? YES

INSPECTION COPY

Signature of owner J. F. Murphy

29361

Permit No. 43
Location 536 Cumberland Ave
Owner J. F. Murphy
Date of permit 3/1/53
Notif. closing-in
Inspn. closing-in
Final Notif.
Final Inspn.
Cert. of Occupancy issued

NOTES

Vertical text on the left side of the page, possibly a stamp or label, oriented vertically.



APPLICATION FOR PERMIT
 DEPARTMENT OF BUILDING INSPECTIONS SERVICES
 ELECTRICAL INSTALLATIONS

Date 6/2/ 19 87
 Receipt and Permit number 10733

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:
 The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of
 Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 536 Cumberland Avenue
 OWNER'S NAME: Stan Houston ADDRESS: Same

OUTLETS:	Receptacles _____	Switches _____	Plugmold _____	ft. TOTAL _____	FEES _____
FIXTURES: (number of)	Incandescent _____	Flourescent _____	(not strip) TOTAL _____		
	Strip Flourescent _____	ft. _____			
SERVICES:	Overhead <u>x</u> _____	Underground _____	Temporary _____	TOTAL amperes <u>500</u>	
METERS: (number of)	<u>5</u> at 100 amp _____				
MOTORS: (number of)	Fractional _____				<u>6.00</u>
	1 HP or over _____				
RESIDENTIAL HEATING:	Oil or Gas (number of units) _____				
	Electric (number of rooms) _____				
COMMERCIAL OR INDUSTRIAL HEATING:	Oil or Gas (by a main boiler) _____				
	Oil or Gas (by separate units) _____				
	Electric Under 20 kws _____	Over 20 kws _____			
APPLIANCES: (number of)	Ranges _____	Water Heaters _____			
	Cook Tops _____	Disposals _____			
	Wall Ovens _____	Dishwashers _____			
	Dryers _____	Compactors _____			
	Fans _____	Others (denote) _____			
	TOTAL _____				
MISCELLANEOUS: (number of)	Branch Panels _____				
	Transformers _____				
	Air Conditioners Central Unit _____	Separate Units (windows) _____			
	Signs 20 sq. ft. and under _____	Over 20 sq. ft. _____			
	Swimming Pools Above Ground _____	In Ground _____			
	Fire/Burglar Alarms Residential _____	Commercial _____			
	Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under _____	over 30 amps _____			
	Circus, Fairs, etc. _____				
	Alterations to wires <u>5</u> _____				<u>2.00</u>
	Repairs after fire _____				
	Emergency Lights, battery _____				
	Emergency Generators _____				
	FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT _____	INSTALLATION FEE DUE: _____			
	FOR REMOVAL OF A "STOP ORDER" (304-16.b) _____	DOUBLE FEE DUE: _____			
		TOTAL AMOUNT DUE: _____			<u>8.00</u>

INSPECTION: Will be ready on _____, 19____; or Will Call xx
 CONTRACTOR'S NAME: Rudy A. Clark
 ADDRESS: 22 South Street, Portland, Maine
 TEL: 774-8970
 MASTER LICENSE NO.: 10745 SIGNATURE OF CONTRACTOR: Rudy A. Clark
 LIMITED LICENSE NO.: _____

INSPECTOR'S COPY — WHITE
 OFFICE COPY — CANARY
 CONTRACTOR'S COPY — GREEN

