6 Canterbury Pines Drive andrew@collinsconsult.net
Gorham, ME 04038 www.collinsconsult.net
(207) 939-6406

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 07/27/17

2 IMG_0168 Date Taken: 5/22/2017 Taken By: ANDREW

Garage doors previously filled and carry 2 sets each crank windows as shown on drawing.