Ann Machado - 236 STATE ST Housing Inspection Report

Reviewed for Code Compliance
Inspections Division
Approved with Conditions

Date: 07/11/14

From: Donald McPherson
To: Jtallks@Gmail.Com
Date: 9/6/2013 9:05 AM
Subject: 236 STATE ST Housing Inspection Report
CC: Ann Machado; Brian Laflamme; John Martell

Jill,
This is a list of the Housing corrections from our inspection.

#3
Graspable handrail to 2nd floor
Fall protection at deck (2 locations) and interior stair
? Chimney at deck Gas water heater
Lock on door from deck to interior

Repair balustrade to second floor

Rear stair repair and guard/handrail

Basement stair guard/handrail

There may be additional corrections from Fire and Electrical departments.

Don McPherson
Code Enforcement Officer

City of Portland
Planning and Urban Development Department
Inspection Services Division
389 Congress St. Rm 315
Portland, ME 04101
Office: 207.874.8705
Support Staff: 207.874.8701
DMcPherson@portlandmaine.gov