CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date 03/20/2006	
Casco Holdings Llc		Peter Merrow		
Locatation	CBL	Status	Inspection Type	
138 PARK AVE	048 A005001		Complaint-Housing Inspection	

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date			
1)	6-113.5 Violation: Notes:	Interior Maintenance of lighting fixtures Light fixture not working			Entry Way				
2)	6-111.4 Violation: Notes:	Interior Maintenance of plumbing fixtures. Toilet loose	2	3	Bathroom				
3)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors Missing ceiling tiles	2	3	Various locati	ons			
4)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors Hole in ceiling, Must be repaired	2	3	Dining Room				
5)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors Hole in bedroom door, must be repaired or	2 replaced.	3	Bedroom				
6)	6-108.3 Violation: Notes:	Interior Exterior windows, doors and skylights Repair/replace torn screens.			Various locati	ons			
7)	6-113.5 Violation: Notes:	Interior Maintenance of lighting fixtures Light fixture is broken in rear entry.			Rear Entry				
8)	6-108.1 Violation: Notes:	Exterior Foundations cellars, exterior walls, roofs peeling siding			rear wall				
9)	6-109.5 Violation: Notes:	Interior 2-3 4 and 6 Various locations Rodent and vermin control. BedBugs, must have licensed pest control operator treat properly.							
Co	Comments: Violations must be corrected with in 30 Days of this notice.								