



Yes. Life's good here.

Planning & Urban Development Department

Director of Planning and Urban Development leff Levine

> Inspection Services, Director Tammy M. Munson

November 13, 2015

**GRAY TIMOTHY S &** 107 GRANT ST PORTLAND, ME 04102

## CBL: 048 A024001 Located at: 107 GRANT ST

### Certified Mail 70101870000281368114

Dear Gray Timothy S &,

SECOND NOTICE OF VIOLATION - BILLING NOTIFICATION

An evaluation of the above-referenced property on 07/24/2015 revealed that the struture remains non-compliant with the Housing Code of the City of Portland.

Attached is a list of the violations.

This is a SECOND notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected. A re-inspection will occur on 11/20/2015, at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A M.R.S.A ss 4452.

Please be advised that because this is the second inspection and there are repeat violations, Section 6.2 of the Code requires that you pay a \$150.00 re-inspection fee. This must be paid prior to reinspection. Failure to pay the assessed fee within 30 days shall cause the City to assess lien against the property pursuant to Section 1-16 of the Code. Please feel free to contact me at (207) 874-8703 you wish to discuss this matter further or have any questions.

Sincerely

Doug Morin

Code Enforcement Officer (207) 874-8705

# CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

## **INVOICE FOR FEES**

Applicant:	Gray Timothy S &			
Location:	107 GRANT ST			
CBL:	048 A024001			
<b>Invoice Date:</b>	11/13/2015			


Fee Description		Fee Charge
07/24/2015 HOUSING REINSPECTION		\$150.00
	Amount Due Now:	\$150.00

Detach and remit with payment

CBL 048 A024001 Invoice Date: 11/13/2015 Invoice No: 3017 Total Amt Due: \$150.00 Payment Amount:

Bill to: Gray Timothy S &

Make checks payable to the City of Portland, Inspections Division, Room 315, 389 Congress Street, Portland, ME 04101.





Yes. Life's good here.

Planning & Urban Development Department

July 20, 2015

GRAY TIMOTHY S & 107 GRANT ST PORTLAND, ME 04102

CERTIFIED MAIL: 70101870000281368176

CBL 048 A024001 Located At: 107 Grant St.

#### Notice of Violation/ Tenant Notification

Dear Timothy Gray:

An evaluation of the above-referenced property with Officials from the City's Inspections Division on 07/17/2015 revealed that the structure fails to comply with § 6-108 (d) and § 6-116 (b), of the Housing Code of the City of Portland. Specifically, the damaged and decayed portions of the building and front and rear three (3) level exterior porches must be demolished, and or repaired in accordance with the City of Portland Building Code (MUBEC). Furthermore, the 1st through 3rd Floor front and rear (non-egress) porches must remain vacated and secured from tenant use, and the stored items in the interior hallways and stairwells must be removed immediately.

Given the present circumstances of this Property:

- 1. The building's exterior porches must remain totally vacated and properly secured from tenant use.
- 2. Submit a building permit electronically, for the demolition, or repair of the exterior porches and interior rear stairwell to the Building Inspections Office by 08/03/2015.
  - a. Note: The City may require the building Owner to engage and designate on the building permit application a registered design professional who shall act as the registered design professional in responsible charge. The design professional in responsible charge shall be responsible for reviewing and coordinating submittal documents prepared by others, including phased and deferred submittal items, for compatibility with the design of the building.
- 3. Follow all inspection requirements outlined in each permit issued by the City.

No tenant(s) may occupy the exterior rear porches until further notice from the City. A re-evaluation and inspection of the property will occur on 07/24/2015.

389 Congress Street / www.portlandmaine.gov / tel, 207+874+8703 / tty, 207+874+8936 / fax, 207+874+8716



Planning & Urban Development Department

The City's Corporation Counsel's Office has been alerted to the existence of this matter and intends to pursue legal action including injunctive relief and civil penalties, as provided for in § 1-15 of the Portland City Code and in Title 30-A of M.R.S.A § 4452.

This letter constitutes a decision from which you may appeal pursuant to§ 6-127 of the Portland City Code and Rule 80B of the Maine Rules of Civil Procedure.

If you have any questions, concerns or require emergency repair permits- please contact me at 207-874-8701.

Sincerely, Jonathan Rioux Deputy Director of Inspections

cc: Tenants of 107 Grant St. via Hand Delivery Adam R. Lee, Associate Corporation Counsel Keith Gautreau, Assistant Chief of Fire Prevention and Community Outreach

389 Congress Street / www.portlandmaine.gov / tel, 207+874+8703 / tty, 207+874+8936 / fax, 207+874+8716

# **CITY OF PORTLAND**

**DEPARTMENT OF PLANNING & URBAN DEVELOPMENT** 

389 Congress Street Portland, Maine 04101

# **Inspection Violations**

Owner/Manager GRAY TIMOTHY S &			Inspector Doug Morin		li	Inspection Date 7/17/2015		
Location CBL		Status		li	nspection Type			
107 GRANT ST 048 A0240		024001	Violations Exist		C	Complaint-Inspection		
Code	Int	/Ext	Floor	Unit No.	Area		Compliance Date	
1) 6-109.5.(c	i) Ex	terior			Deck			
Violation:	STAIRWAYS, STAIRS, & PORCHES.; Stairways, stairs, porches. Every outside stairway, stairwell, stairs and porch and any appurtenances thereto shall be structurally sound, in good repair and safe to use.Every outside stairway, stairwell, stairs and porch and any appurtenances thereto shall be structurally sound, in good repair and safe to use.							
Notes:	Rear deck/porches are deteriorated, guards are fallinhg off, upright supports are bowed and decks sagging. Front decks appear to be detriorating as well. Dececk boards are lifting up, gurads look weak and entire structure should be evaluated.							
2) 6-116.(b)	Int	erior			Stairway	ays		
Violation:	EGRESS; EVERY DWELLING UNIT AND EVERY ROOMING UNIT SHALL HAVE SAFE, UNOBSTRUCTED MEANS OF EGRESS LEADING TO SAFE AND OPEN SPACES AT GROUND LEVEL IN ACCORDANCE WITH APPLICABLE STATUTES, REGULATIONS AND ORDINANCES.							
Notes:	Tenants blocking the stairway by storing belongings outside of apartment.							
Comments:	Unsafe Decks.	See Vi	olations					