CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager			Inspector	•		Inspection Date 01/13/2006	
TRUSSELL PROPERTIES LLC			Tom Markley	Tom Markley			
Locatation CBL		Status	Status		Inspection Type		
84 PARK AVE 048 B005001		Re-Inspect 30 Days		Complaint-Inspection			
Code	Int/Ext		Floor	Unit No.	Area	Compliance Date	
1) 6-108.3							
	Exterior windows, doors and skylights						
	Window to air shaft broken.						
2)							
Violation:	Maintenance of lighting fixtures						
Notes:	Light fixture in kitchen needs to be repaired/replaced.						
3) 6-116.5	Interior		3	6	Hall		
	Fire Protection	on					
	Smoke detec	ctor is covered in p	paint.				
4)	Interior		3	6	Front Room		
	Interior floors	s, walls, ceilings ar	nd doors				
	Holes in she	etrock wall/cracke	d plaster.				
5)							
	Maintenance	of plumbing fixtur	es.				
	Toilet is clog	ged with misc. de	bris.				
6)	Interior		3	6	Various locat	ions	
Violation:	Sanitiation/Maintenance of assigned areas.						
Notes:	General sanitation of entire apartment. Trash and other debris spread through out						

must be done in 30 days.