
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

| | | | |
|------------------------------------|---------------------------|-------------------------------------|--|
| Owner/Manager Roy Bagley | | Inspector Marland Wing | Inspection Date 8/23/2005 |
| Locatation 142 GRANT ST | CBL 048 C001001 | Status Re-Inspect 30 Days | Inspection Type Complaint-Housing Inspection |

| Code | Int/Ext | Floor | Unit No. | Area | Compliance Date |
|-------------------|--|--------------|-----------------|-------------|------------------------|
| 1) 6-108.2 | Interior | 1 | 6 | Bedroom | |
| Violation: | Interior floors, walls, ceilings and doors | | | | |
| Notes: | Front & Rear bedroom ceilings sagging titles | | | | |
| 2) 6-108.2 | Interior | 1 | 6 | Bedroom | |
| Violation: | Interior floors, walls, ceilings and doors | | | | |
| Notes: | Front & Rear bedroom Signs of leakage | | | | |
| 3) 6-108.2 | Interior | 1 | 6 | Kitchen | |
| Violation: | Interior floors, walls, ceilings and doors | | | | |
| Notes: | kitchen ceiling signs of leakage | | | | |

Comments: