

563 CUMBERLAND AVE.

LONGF-SQ II



#8503-57

FB

● SENDER: Complete items 1, 2, 3, and 4.
 Add your address in the "RETURN TO" space
 on reverse.

(CONSULT POSTMASTER FOR FEES)

1. The following service is requested (check one).

Show to whom and date delivered —¢
 Show to whom, date, and address of delivery —¢
 RESTRICTED DELIVERY —¢
(The restricted delivery fee is charged in addition to the return receipt fee.)

TOTAL \$ _____

3. ARTICLE ADDRESSED TO:
 Mr. Paul Rheume, Sr.
 52 Fessenden Street
 Portland, Maine 04103

4. TYPE OF SERVICE:

<input type="checkbox"/> REGISTERED	<input type="checkbox"/> INSURED	ARTICLE NUMBER 934 906
<input checked="" type="checkbox"/> CERTIFIED	<input type="checkbox"/> COD	
<input type="checkbox"/> EXPRESS MAIL		

(Always obtain signature of addressee or agent)

I have received the article described above.

SIGNATURE Addressee Authorized agent

5. DATE OF DELIVERY: 9/25

6. ADDRESSEE'S ADDRESS (Only if requested)

7. UNABLE TO DELIVER BECAUSE:

7a. EMPLOYEE'S INITIALS:

Re: 563 Cumb. Ave. — B. MacIsaac
 RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

PS Form 3811, Jan. 1979

SENDER: Complete items 1, 2, and 3. Add your address in the "RETURN TO" space on reverse.

1. The following service is requested (check one.)

Show to whom and date delivered.....

Show to whom, date and address of delivery.....

RESTRICTED DELIVERY
Show to whom and date delivered.....

RESTRICTED DELIVERY.
Show to whom, date, and address of delivery.....

(CONSULT POSTMASTER FOR FEES)

2. ARTICLE ADDRESSED TO:

Mr. Paul Rheau
52 Fessenden Street
Portland, Maine 04103

3. ARTICLE DESCRIPTION:

REGISTERED NO.	CERTIFIED NO.	INSURED NO.
	0925641	

Always obtain signature of addressee or agent.

I have received the article described above.

SIGNATURE Addressee Authorized agent

Paul Rheau

4. DATE OF DELIVERY

5. ADDRESS (Complete only if requested)

6. UNABLE TO DELIVER BECAUSE:

INITIALS

POST OFFICE
JUN 29 1982
U.S. POST OFFICE

☆ GPO : 1979-300-459

Re: 563 Cumberland Ave. - Hugh

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

PS Form 3811, Jan. 1979

SENDER: Complete items 1, 2, and 3. Add your address in the "RETURN TO" space on reverse.

1. The following service is requested (check one.)

Show to whom and date delivered.....

Show to whom, date and address of delivery.....

RESTRICTED DELIVERY
Show to whom and date delivered.....

RESTRICTED DELIVERY.
Show to whom, date, and address of delivery.....

(CONSULT POSTMASTER FOR FEES)

2. ARTICLE ADDRESSED TO:
Mr. Paul Rheume
52 Fessenden St.
Portland, Me 04103

ARTICLE DESCRIPTION:
REGISTERED NO. CERTIFIED NO. INSURED NO.
09-5621

(Always obtain signature of addressee or agent)

I have received the article described above.

SIGNATURE Addressee Authorized agent

DATE OF DELIVERY 6/4/87

POSTMARK

3. ADDRESS (Complete only if requested)

4. UNABLE TO DELIVER BECAUSE:

CLERK'S INITIALS

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

Re: 563 Cumb. Ave. - Leary

CERTIFICATE
OF
COMPLIANCE

January 7, 1980 ✓

CITY OF PORTLAND

Department of Neighborhood Conservation
Housing Inspections Division
Telephone: 775-5451 - Extension 448 - 358

Mr. Paul Rheame
52 Fessenden Street
Portland, Maine 04103

Re: Premises located at 53 Cumberland Avenue, Portland, Maine 48-E-17 NCP-11

Dear Mr. Rheame:

A re-inspection of the premises noted above was made on 12/31/79
by Housing Inspector Leary.

This is to certify that you have complied with our request to correct the violation of the Municipal Codes relating to housing conditions as described in our "Notice of Housing Conditions" dated 3/26/79.

Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.

In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to inspect each residential building at least once every five years. Although a property is subject to re-inspection at any time during the said five year period, the next regular inspection of this property is scheduled for January 1985.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle D. Moyes
Lyle D. Moyes,
Chief of Housing Inspections

Inspector M. Leary

M. Leary

dld

563 CUMBERLAND AVE.

HOUSTON





CITY OF PORTLAND

JOSEPH E. McDONOUGH
FIRE CHIEF

January 25, 1984

Gloria R. & Paul R. Rheume
52 Fessenden Street
Portland, Maine 04103

OK
1-30-84

Re: Smoke Detectors

Dear Mr. & Mrs. Rheume:

During a recent inspection of the property owned by you at 563 Cumberland Avenue, it was noted that smoke detectors were missing in the following areas:

Basement Apt. - #1
Basement Apt. - #2

25 MRSA §2464 requires that approved smoke detectors be installed in each of the above listed areas. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in ten (10) days. Lack of compliance will result in referral of the matter for legal action.

Sincerely yours,
Joseph E. McDonough
Chief of the Fire Department
City of Portland

Eurton MacIsaac : Enforcement
Officer (6)

cc: Lt. James Collins, Fire Prevention Bureau

jmr

563 CUMBERLAND AVE.

Houston



- 013
034

NOTICE OF HOUSING CONDITIONS

CITY OF PORTLAND, MAINE

Department of Planning & Urban Development
Inspection Services Division
Tel. 775-5451 - Ext. 311 - 318 - 319

Gloria R. & Paul R. Rheume, Jts.
52 Fessenden Street
Portland, Maine 04103

DU 11

CH. 45 BLK. E LOT 31

LOCATION: 563 Cumberland Ave.

PROJECT: NCP-WE
ISSUED: February 1, 1984
EXPIRES: April 1, 1984

Dear Mr. & Mrs. Rheume:

You are hereby notified, as owner or agent, that an inspection was made of the premises at 563 Cumberland Avenue by Code Enforcement Officer Burton MacIsaac. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspection Report".

In accordance with the provisions of the above-mentioned Code, you are hereby ordered to correct those defects on or before April 1, 1984. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.

Please Note: You should consult the inspection Services Division to insure that any corrective action you undertake complies with the building, plumbing, electrical, zoning and any other Article of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in its goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours,

Joseph E. Gray, Jr., Director
Planning & Urban Development

By: Lyle D. Woyes
Lyle D. Woyes
Inspection Services Division

Burton MacIsaac
Code Enforcement Officer - Burton MacIsaac (6)

Attachments

jmr

HOUSING INSPECTION REPORT

OWNER: Gloria R. & Paul R. Rheame, Jts. LOCATION: 563 Cumberland Ave. 48-E-31 WE

CODE ENFORCEMENT OFFICER: Burton MacIsaac (6)

HOUSING CONDITIONS DATED: Feb. 1, 1984 , EXPIRES: Apr. 1, 1984

ITEMS LISTED BELOW ARE IN VIOLATION OF ARTICLE V OF THE MUNICIPAL CODES, "HOUSING CODE", AND MUST BE CORRECTED ON OR BEFORE THE EXPIRATION DATE.

	<u>SEC. (S)</u>
1. SECOND FLOOR FRONT HALL - wall - broken plaster.	108-2
2. SECOND FLOOR FRONT HALL - rail - missing balusters.	108-4
<u>FIRST FLOOR - APT. #3</u>	
3. BATHROOM - tub - cross connection.	111-1
<u>SECOND FLOOR - APT. #8</u>	
4. BATHROOM - wall - broken plaster.	108-2
<u>THIRD FLOOR - APT. #9</u>	
5. BATHROOM - tub - cross connection.	111-1
<u>THIRD FLOOR - APT. #10</u>	
6. LIVING ROOM - wall - peeling paint.	108-2
7. BATHROOM - wall - broken plaster.	108-2

NOTICE OF HOUSING CONDITIONS

CITY OF PORTLAND, MAINE

Department of Planning & Urban Development
Inspection Services Division
Tel. 775-5451 - Ext. 311 - 318 - 319

Gloria R. & Paul R. Rheame, Jts.
52 Fessenden Street
Portland, Maine 04103

LD 11

CH. 48 BLK. F LOT 31

LOCATION: 563 Cumberland Ave.

PROJECT: NCP-WE
ISSUED: February 1, 1984
EXPIRES: April 1, 1984

Dear Mr. & Mrs. Rheame:

You are hereby notified, as owner or agent, that an inspection was made of the premises at 563 Cumberland Avenue by Code Enforcement Officer Burton MacIsaac. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspection Report".

In accordance with the provisions of the above-mentioned Code, you are hereby ordered to correct those defects on or before April 1, 1984. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.

Please Note: You should consult the inspection Services Division to insure that any corrective action you undertake complies with the building, plumbing, electrical, zoning and any other Article of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in its goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours,

Joseph E. Gray, Jr., Director
Planning & Urban Development

By: Lyle D. Noyes
Lyle D. Noyes
Inspection Services Division

Burton MacIsaac
Code Enforcement Officer - Burton MacIsaac (6)

Attachments

jmr

HOUSING INSPECTION REPORT

OWNER: Gloria R. & Paul R. Rheame, Jts. LOCATION: 563 Cumberland Ave. 48-E-21 SE

CODE ENFORCEMENT OFFICER: Burton Marisaac (6)

HOUSING CONDITIONS DATED: Feb. 1, 1984 , EXPIRES: Apr. 1, 1984

ITEMS LISTED BELOW ARE IN VIOLATION OF ARTICLE V OF THE MUNICIPAL CODES, "HOUSING CODE", AND MUST BE CORRECTED ON OR BEFORE THE EXPIRATION DATE.

	<u>SEC. (S)</u>
1. SECOND FLOOR FRONT HALL - wall - broken plaster.	108-2
2. SECOND FLOOR FRONT HALL - rail - missing baluster.	108-4
<u>FIRST FLOOR - APT. #3</u>	
3. BATHROOM - tub - cross connection.	111-1
<u>SECOND FLOOR - APT. #8</u>	
4. BATHROOM - wall - broken plaster.	108-2
<u>THIRD FLOOR - APT. #9</u>	
5. BATHROOM - tub - cross connection.	111-1
<u>THIRD FLOOR - APT. #10</u>	
6. LIVING ROOM - wall - peeling paint.	108-2
7. BATHROOM - wall - broken plaster.	108-2

CERTIFICATE
OF
COMPLIANCE

DATE: April 24, 1984

DU: 11

CITY OF PORTLAND

Department of Planning & Urban Development
Housing Inspections Division
Telephone: 775-5451 - Extension 311 - 318

Gloria R. & Paul R. Rheame, Jts.
52 Fessenden Street
Portland, Maine 04103

Re: Premises located at 563 Cumberland Ave. 48-E-31 WE

Dear Mr. & Mrs. Rheame:

A re-inspection of the premises noted above was made on April 19, 1984
by Code Enforcement Officer Burton MacIsaac.


This is to certify that you have complied with our request to correct the violation of
the Municipal Codes relating to housing conditions as described in our "Notice of Housing
Conditions" dated February 1, 1984.

Thank you for your cooperation and your efforts to help us maintain decent, safe and
sanitary housing for all Portland residents.

In order to aid in the preservation of Portland's existing housing
inventory, it shall be the policy of this department to inspect each
residential building at least once every five years. Although a
property is subject to re-inspection at any time during the said
five-year period, the next regular inspection of this property is
scheduled for April 1989.

Sincerely yours,

Joseph E. Gray, Jr., Director of
Planning and Urban Development

By 
P. Samuel Hoffses,
Chief of Inspection Services



Code Enforcement Officer - Burton MacIsaac (6)

jm

NOTICE OF HOUSING CONDITIONS

CITY OF PORTLAND, MAINE

Department of Planning & Urban Development
Inspection Services Division
Tel. 775-5451 - Ext. 311 - 318 - 319

Gloria R. & Paul R. Rheaume, Jts.
52 Fessenden Street
Portland, Maine 04103

DU 11

CH. 48 BLK. E LOT 31

LOCATION: 563 Cumberland Ave.

PROJECT: NCP-WE
ISSUED: February 1, 1984
EXP RES: April 1, 1984

Dear Mr. & Mrs. Rheaume:

You are hereby notified, as owner or agent, that an inspection was made of the premises at 563 Cumberland Avenue by Code Enforcement Officer Burton MacIsaac. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspection Report".

In accordance with the provisions of the above-mentioned Code, you are hereby ordered to correct those defects on or before April 1, 1984. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.

Please Note: You should consult the Inspection Services Division to insure that any corrective action you undertake complies with the building, plumbing, electrical, zoning and any other Article of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours,

Joseph E. Gray, Jr., Director
Planning & Urban Development

By: _____
Lyle D. Noyes
Inspection Services Division

Code Enforcement Officer - Burton MacIsaac (6)

Attachments

jmr

HOUSING INSPECTION REPORT

OWNER: Gloria R. & Paul R. Rheume, Jts. LOCATION: 563 Cumberland Ave. 48-E-31 WE
CODE ENFORCEMENT OFFICER: Burton MacIsaac (6)

HOUSING CONDITIONS DATED: Feb. 1, 1984 , EXPIRES: Apr. 1, 1984

ITEMS LISTED BELOW ARE IN VIOLATION OF ARTICLE V OF THE MUNICIPAL CODES, "HOUSING CODE",
AND MUST BE CORRECTED ON OR BEFORE THE EXPIRATION DATE.

1. SECOND FLOOR FRONT HALL - wall - broken plaster.	OK 4-18	SEC. (S)
2. SECOND FLOOR FRONT HALL - rail - missing balusters.	OK 4-18	108-2
108-4		
FIRST FLOOR - APT. #3		
3. BATHROOM - tub - cross-connection.	OK 4-19	111-1
SECOND FLOOR - APT. #8		
4. BATHROOM - wall - broken plaster.	OK 4-18	108-2
THIRD FLOOR - APT. #9		
5. BATHROOM - tub - cross-connection.	4-19	111-1
THIRD FLOOR - APT. #10		
6. LIVING ROOM - wall - peeling paint.	OK 4-18	108-2
7. BATHROOM - wall - broken plaster.	OK 4-18	108-2



CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT
INSPECTION SERVICES DIVISION

NOTICE OF HOUSING CONDITIONS

DU:
CHART-BLOCK-LOT - 48-E-17
LOCATION: 559-565 Cumberland Avenue (PARKSIDE)

DISTRICT: 6
ISSUED: July 31, 1990
EXPIRES: October 1, 1990

Paul R. Rheume
52 Fessenden Street
Portland, ME 04103

Dear Mr. Rheume:

You are hereby notified, as owner or agent, that an inspection was made of the premises at 559-565 Cumberland Avenue by Code Enforcement Officer A. Rowe for K. Carroll. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspection Report".

In accordance with the provisions of the above mentioned Code, you are hereby ordered to correct those defects on or before October 1, 1990. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code Standards.


Please Note: You should consult the inspection Services Division to insure that any corrective action you undertake complies with the building, plumbing, electrical, zoning and other Article of the City Code.


Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in it's goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Very truly yours,

Joseph E. Gray, Jr., Director
Planning & Urban Development

By: 
Samuel Hoffses
Chief of Inspection Services


Arthur Rowe for Kevin Carroll (6)
Code Enforcement Officer

Attachments

jmr 399 CONGRESS STREET • PORTLAND, MAINE 04101 • TELEPHONE (207) 874-8300

HOUSING INSPECTION REPORT

OWNER: Paul R. Rheaume

LOCATION: 559-565 Cumberland Ave. 48-E-17

CODE ENFORCEMENT OFFICER: Arthur Rowe for Kevin Carroll (6)

HOUSING CONDITIONS DATED: July 31, 1990

EXPIRES: October 1, 1990

ITEMS LISTED BELOW ARE IN VIOLATION OF ARTICLE V OF THE MUNICIPAL CODES, "HOUSING CODE", AND MUST BE CORRECTED ON OR BEFORE THE EXPIRATION DATE.

SEC. (S)

1. INTERIOR BASEMENT HALL - damaged wall.
2. INTERIOR BASEMENT HALL - stairs - missing balusters.
3. INTERIOR CELLAR - asbestos - pipe lagging.
- *4. INTERIOR - APARTMENT #2 - missing smoke detector.
- *5. INTERIOR - APARTMENT #3 - missing smoke detector.
- *6. INTERIOR - APARTMENT #5 - missing smoke detector.

*See attached smoke detector letter. 24 hours from receipt of this notice to correct.



CITY OF PORTLAND, MAINE

389 CONGRESS STREET
PORTLAND, MAINE 04101
(207) 775-5451

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

P. SAMUEL HOFFSES, CHIEF
INSPECTION SERVICES DIVISION

Date: July 31, 1990

Paul R. Rheaume
52 Fessenden Street
Portland, ME 04103

Re: Smoke Detectors

Dear Mr. Rheaume:

During a recent inspection of the property owned by you at 559-565 Cumberland Avenue, Portland, Maine, it was noted that smoke detectors were missing/inoperable in some locations.


25 M.R.S.A. 2464 requires that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When actuated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in ten (24) hrs. . Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Sincerely yours,

Joseph E. Gray, Jr., Director
Planning & Urban Development

By: 
P. Samuel Hoffses
Chief of Inspection Services

Arthur Rowe for Kevin Carroll (6)
Code Enforcement Officer

cc: Lt. James P. Collins, Fire Prevention Bureau

jmr

Inspection Services
Samuel P. Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

August 04, 1994

RHEAUME PAUL R
52 FESSENDEN ST
PORTLAND ME 04103

Re: 563 Cumberland Ave
CBL: 048- - E-017-001-01
DU: 11

Dear Mr. Rheaume:

During a recent inspection of the property owned by you at the above referred address, it was noted that smoke detectors were inoperative in Apartment #6.

25 MRSA 2464 required that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When activated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Re-inspection of your property will be made in 24 hours. Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Sincerely,

Marland Wing
Code Enforcement Officer

Marge Schaubkal
Asst. Chief of Inspection Services

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

DECEMBER 12, 1996

RHEAUME PAUL R
52 FESSENDEN ST
PORTLAND ME 04103

Re: 583 CUMBERLAND AVE
CBL: 048 - E-017-001-01
DU: 11

Dear Mr. Rheaume:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above-referred property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems:

- | | |
|--|--------|
| 1. EXT - RIGHT - TRIM -
MOLDING IS MISSING | 108.10 |
| 2. EXT - OVERALL -
TRIM HAS PEELING PAINT | 108.10 |
| 3. EXT - BASEMENT - FRONT -
WINDOW HAS BROKEN GLASS | 108.30 |

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,

Marland Wing
Code Enforcement Officer

Tammy Munson
Code Enfc. Offc./ Field Supv.

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

SEPTEMBER 04, 1996

CITY OF PORTLAND

RHEAUME PAUL R
52 FESSENDEN ST
PORTLAND ME 04103

Re: 563 CUMBERLAND AVE
CBL: 048- - E-017-001-01
DU: 11

Dear Mr. Rheume:

We recently received a complaint, and an inspection was made at the above-referenced address. As a result of the inspection, you are hereby notified to correct the following substandard housing conditions:

- | | |
|---|--------|
| 1. INT - 1ST FL - APT #3 - BATHROOM
WALL HAS A LOOSE LIGHT SWITCH | 113.50 |
| 2. INT - 1ST FL - APT #3 - KITCHEN
WALL HAS A LOOSE RECEPTACLE | 113.50 |
| 3. INT - 1ST FL - APT #3 -
SMOKE DETECTORS ARE INOPERATIVE
--TWENTY-FOUR (24) HOURS TO CORRECT -- | 113.50 |
| 4. INT - 1ST FL - APT #3 - LIVING ROOM
CEILING HAS A LOOSE LIGHT FIXTURE | 108.50 |
| 5. INT - 1ST FL - APT #3 - LIVING ROOM
WALL HAS LOOSE PANELING | 108.50 |
| 6. INT - 1ST FL - APT #3 - FRONT BEDROOM
WALL HAS LOOSE PANELING | 108.20 |

The above-mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected within thirty (30) days. Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely,

Marland Wing
Marland Wing
Code Enforcement Officer

Tammy Munson
Tammy Munson
Code Enfc. Offr./ Field Supv.

