

CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager TRUSSELL PROPERTIES LLC		Inspector Peter Merrow	Inspection Date 1/10/2006
Location 507 CUMBERLAND AVE	CBL 048 F018001	Status Re-Inspect 30 Days	Inspection Type Complaint-

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-108.2	Interior		1	Various locations	
Violation:	Interior floors, walls, ceilings and doors				
Notes:	Hole in Livingroom ceiling				
2) 6-109.5	Interior		1	Various locations	
Violation:	Rodent and vermin control.				
Notes:	Infestation -Bed Bugs				
3) 6-108.2	Interior		1	Various locations	
Violation:	Interior floors, walls, ceilings and doors				
Notes:	Torn Carpet through out the unit				
4) 6-108.2	Interior		1	Kitchen	
Violation:	Interior floors, walls, ceilings and doors				
Notes:	Kitchen Floor tiles seperated from floor				
5) 6-111.4	Interior		1	Bathroom	
Violation:	Maintenance of plumbing fixtures.				
Notes:	Bathroom Vanity needs Repair/ replace in disrepair				

Comments: Vehicle must be removed, building secured, and violation repaired