DISPLAY THIS CARD ON PRINCIPAL FRONTAGE OF WORK



This is to certify that

BK PROPERTIES, LLC - KARGAR

Located at

185 GRANT ST

PERMIT ID: 2013-01984

ISSUE DATE: 10/18/2013

CBL: 053 B017001

has permission to renovations for new tenants

provided that the person or persons, firm or corporation accepting this permit shall comply with all of the provisions of the Statues of Maine and of the Ordinances of the City of Portland regulating the construction, maintenance and use of the buildings and structures, and of the application on file in the department.

Notification of inspection and written permission procured before this building or part thereof is lathed or otherwise clsoed-in. 48 HOUR NOTICE IS REQUIRED.

A final inspection must be completed by owner before this building or part thereof is occupied. If a certificate of occupancy is required, it must be procured prior to occupancy.

/s/ Chris Pirone /s/ Tammy Munson

Fire Official Building Official

THIS CARD MUST BE POSTED ON THE STREET SIDE OF THE PROPERTY THERE IS A PENALTY FOR REMOVING THIS CARD

Approved Property Use - Zoning

pre-1957 Assessors show this to be a four (4) residential building - Section 14-387 may allow them to keep this nonconformity

Building Inspections

Fire Department
Classification:
Apartment Building
ENTIRE

2009 NFPA

BUILDING PERMIT INSPECTION PROCEDURES Please call 874-8703 (ONLY)

or email: buildinginspections@portlandmaine.gov

Check the Status or Schedule an Inspection On-Line at http://www.portlandmaine.gov/planning/permitstatus.asp

With the issuance of this permit, the owner, builder or their designee is required to provide adequate notice to the city of Portland Inspections Services for the following inspections. Appointments must be requested 48 to 72 hours in advance of the required inspection. The inspection date will need to be confirmed by this office.

- Please read the conditions of approval that is attached to this permit!! Contact this office if you have any questions.
- Permits expire in 6 months. If the project is not started or ceases for 6 months.
- If the inspection requirements are not followed as stated below additional fees may be incurred due to the issuance of a "Stop Work Order" and subsequent release to continue.
- Per Section 107.3.1 of the Maine Uniform Building and Energy Code (MUBEC). One set of printed approved stamped construction documents shall be kept at the site of work and shall be open to inspection by building officials.

REQUIRED INSPECTIONS:

Close-in Plumbing/Framing Electrical Close-in Above Ceiling Inspection Final Inspection

The project cannot move to the next phase prior to the required inspection and approval to continue, REGARDLESS OF THE NOTICE OF CIRCUMSTANCES.

IF THE PERMIT REQUIRES A CERTIFICATE OF OCCUPANCY, IT MUST BE PAID FOR AND ISSUED TO THE OWNER OR DESIGNEE BEFORE THE SPACE MAY BE OCCUPIED.

City of Portland, Maine - Building or Use Permit 389 Congress Street, 04101 Tel: (207) 874-8703, Fax: (207) 874-87			Permit No: 2013-01984	Date Applied For:	CBL:	
				09/04/2013	053 B017001	
Proposed Use:		Proposed Project Description:				
Same: Residential	4 dwelling units	renovat	renovations for new tenants			
Dept: Zoning	Status: Approved	Reviewer:	Marge Schmucka	al Approval Da	nte: 09/13/2013	
Note:					Ok to Issue: 🔽	
Conditions:						
Donts Decilding	Status Assumed of Conditions	Dardaman	T	A managara I Da	10/19/2012	
Dept: Building	Status: Approved w/Conditions	Reviewer:	Tammy Munson	Approval Da		
Note:					Ok to Issue:	
Conditions						

- 1) Hardwired photoelectric interconnected battery backup smoke detectors shall be installed in all bedrooms, protecting the bedrooms, and on every level.
 - The same is required for existing buildings, where permanent wiring is feasible; or at the very least battery operated smoke detectors are required. Verification of this will be upon inspection.
- 2) Permit approved based upon information provided by the applicant or design professional. Any deviation from the final approved plans requires separate review and approval prior to work.
- 3) Carbon Monoxide (CO) alarms shall be installed in each area within or giving access to bedrooms. That detection must be powered by the electrical service (plug-in or hardwired) in the building and battery.
- 4) There must be a 2" clearance maintained between the chimney and any combustible material, with draft stopping per code at each level.
- 5) All floors and walls that separate dwelling units or dwelling units and common areas are required to meet a 1 hour fire rated assembly and sound transmission rating of 45 STC.
- 6) All penetrations between dwelling units and dwelling units and common areas shall be protected with approved firestop materials, and recessed lighting/vent fixtures shall not reduce the (1 hour) required rating per Sec. 713 of IBC or R317.3.1.2 of the IRC.
- 7) Penetrations through fire resistance rated assemblies shall be protected by an approved penetration firestop system installed as tested in accordance with ASTM E814 or UL 1479
- 8) Separate permits are required for any electrical, plumbing, sprinkler, fire alarm, HVAC systems, heating appliances, including pellet/wood stoves, commercial hood exhaust systems and fuel tanks. Separate plans may need to be submitted for approval as a part of this process.

 Dept:
 Fire
 Status:
 Approved w/Conditions
 Reviewer:
 Chris Pirone
 Approval Date:
 09/30/2013

 Note:
 Ok to Issue:
 ✓

Conditions:

- 1) Construction or installation shall comply with City Code Chapter 10.
- 2) The approved plans with the Building Department Approved stamp shall be maintained on site for inspection.
- 3) Street addresses shall be marked on the structure and shall be as approved by the City E-911 Addressing Officer. Contact Michelle Sweeney at 874-8682 for further information.
- 4) A separate Fire Alarm Permit is required for new systems; or for work effecting more than 5 fire alarm devices; or replacement of a fire alarm panel with a different model. This review does not include approval of fire alarm system design or installation.
- 5) Any cutting and welding done will require a Hot Work Permit from Fire Department.

PERMIT ID: 2013-01984 **Located at:** 185 GRANT ST **CBL:** 053 B017001

- 6) Fire walls, fire barriers, fire partitions, smoke barriers and smoke partitions or any other wall required to have protected openings or penetrations shall be effectively and permanently identified with signs or stenciling in accessible concealed floor, floor-ceiling or attic spaces at intervals not exceeding 30 feet with lettering not less than 0.5 inches in height.
- 7) Notice: The first scheduled final inspection fee is at no charge. Additional inspections shall be billed at \$75 for each inspector.
- 8) Through-penetrations and membrane penetrations in fire walls, fire barrier walls, and fire resistance rated horizontal assemblies shall be protected by firestop systems or devices in conformance with NFPA 101:8.3.5 (ASTM E 814 or ANSI/UL 1479). Providing firestop labels at each firestop system or device and an onsite manual containing the detail for each firestop system or device used for the project will streamline final inspection approvals.
- 9) **The fire alarm system design shall be evaluated for the renovated areas by an NICET IV certified interior fire alarm designer or a licensed engineer for compliance with the code. A compliance letter is required prior to the final inspection.**
 A current inspection sticker from an approved fire alarm inspection company is required prior to the final inspection.
- 10 Shall comply with 2009 NFPA 101 Chapter 31 Existing Apartment Building Occupancies.