



Permitting and Inspections Department
Michael A. Russell, MS, Director

JAWAD ASAL S &
236 FALMOUTH RD
FALMOUTH, ME 04105

CBL: 053 B017001
Located at: 185 GRANT ST

Certified Mail 7015 3010 0000 0201 0853

Dear JAWAD ASAL S &,

An evaluation of the above-referenced property on **08/04/2017** shows that the structure fails to comply with Chapter 6, Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 10 days of the date of this notice. A re-inspection of the premises will occur on **08/15/2017** at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

A handwritten signature in black ink, appearing to read "Matthew Sarapas".

Matthew Sarapas
Code Enforcement Officer

**CITY OF PORTLAND
HOUSING SAFETY OFFICE**

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager JAWAD ASAL S &		Inspector Matthew Sarapas	Inspection Date 8/4/2017
Location 185 GRANT ST	CBL 053 B017001	Status Violations Exist	Inspection Type Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
-------------	----------------	--------------	-----------------	-------------	------------------------

1) 6-108.(c)

Violation: EXTERIOR WINDOWS, DOORS AND SKYLIGHTS; Every window or door, including basement or cellar door and hatchway, and skylight shall be substantially weathertight, watertight, and vermin proof and shall be kept in sound working condition and good repair.

Every exterior window shall include storm sash with screens or an alternative equally effective for heat retention and ventilation purposes, all in operable condition.

Notes: First floor window on left front of building has broken inner pane of glass, needs to be repaired immediately as broken glass presents a safety hazard

2) 55.001

Violation: NFPA 101- 7.5.1.1.1 EXIT(S) OBSTRUCTED; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4.

Notes: Rear stairs blocked with trash bags.

3) 6-109.(d)

Violation: DISPOSAL OF RUBBISH, ASHES, GARBAGE AND WASTE; Separate watertight, tightly covered plastic or metal containers shall be provided, one (1) or more for garbage and other food wastes, one (1) or more for rubbish, paper, and other non food wastes, and one (1) or more metal containers for ashes, and all such containers shall be kept covered at all times so as to prevent the ingress and egress of flies, rats or other animals. Plastic or paper bags or boxes are not considered "containers" for purposes of this section. Ashes shall be cold when placed in containers for collection. Such containers shall be cleaned periodically so that they will not become foul or offensive and shall be placed in convenient locations for removal of the contents by persons authorized to collect the same. Every occupant of a dwelling, dwelling unit, rooming house or rooming unit shall place or cause to be placed all garbage, rubbish and other waste material in such containers and shall not permit any accumulation or deposit of such substances in or about the premises except in said containers. The responsibility for the provision of such containers shall be as follows

1.It shall be the duty of every occupant of every dwelling occupied by not more than two (2) families to provide and keep within the dwelling or upon the premises where the dwelling is situated sufficient containers to meet the above requirements.

2.It shall be the duty of the owner or operator of every multiple dwelling to provide and keep within the dwelling or upon the premises where the dwelling is situated sufficient containers to meet the above requirements.

3.It shall be the duty of every owner or operator of a rooming house to provide and keep within the dwelling or upon the premises where the dwelling is situated sufficient containers to meet the above requirements.

Notes: Rear stairs blocked by torn open, rancid bags of trash, trash is present throughout the exterior as well.

**CITY OF PORTLAND
HOUSING SAFETY OFFICE**

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager JAWAD ASAL S &		Inspector Matthew Sarapas	Inspection Date 8/4/2017
Location 185 GRANT ST	CBL 053 B017001	Status Violations Exist	Inspection Type Inspection

Comments: Owner was not present for confirmed inspection appointment. Violations observed from exterior of property.