CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector		Inspection Date			
DEUTSCH BANK NATIONAL TRUST COMPA		Jon Rioux		6/18/2007			
Locatation CBL State		Status	status		Inspection Type		
833 CONGRESS ST 053 C023001		Passed		Complaint-Inspection			
On the Lord/Foot	•	F1	11-24 NI-	A	0		

	Code	Int/Ext	Floor	Unit No.	Area Compliance Da					
1)	6-120.1 thru	6-120.1 thru 5			Various locations	03/04/2008				
	Violation:	Posted against occupancy.								
	Notes:	Dwelling unit must be totally vacated and secured from vandalism.								
2)	6-108.4	Exterior		Stairways		03/04/2008				
·	Violation:				•					
	Notes:	Every inside and outside stairway, stairwell, stairs, and porch and any appurtenances thereto shall be structurally sound, in good repair, and safe to use.								
			ding permit application must be submitted, indicating repairs needed for the rear exterior stairwell, er to move forward to occupy the structure.							
3)	6-109.1	Interior	3			03/04/2008				
	Violation:									
	Notes:	Maintenance of assigned areas. Every occupant of a dwelling, dwelling unit, or rooming unit shall maintain in a clean and sanitary manner that part of the dwelling, dwelling unit, or rooming unit, and dwelling premises which he or she occupies and controls.								

Comments: