## CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager		Inspector	Inspection Date
DEVINE KATHRYN S &		Jodine Adams	09/16/2004
Locatation	CBL	Status	Inspection Type
1 HORTON PL	055 E019001	Re-Inspect 10 Days	Complaint-Inspection

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1)	6-109.5	Interior	entire	entire	entire	
	Violation:	Rodent and vermin control.				
	Notes:	german cockroaches found throughout				
2)	6-116.5	Interior	1	left	entire	
	Violation:	Fire Protection				
	Notes:	smoke detectors inoperatable				
3)	6-113.5 Exterior				front of building	ng
	Violation:	Maintenance of lighting fixtures				
	Notes:	main electrical feed no secure				
4)	6-108.2	Interior	1	left	Bathroom	
	Violation:	Interior floors, walls, ceilings and doors				
	Notes:	bathroom door missing				

**Comments:**