



Planning & Urban Development Department

Director of Planning and Urban Development
Jeff LevineInspection Services, Director
Tammy M. Munson

July 28, 2015

LODOKA LADO
560 MAIN SST
SOUTH PORTLAND, ME 04106**CBL: 055 E024001**
Located at: 3 HORTON PL**Certified Mail 7010 1870 0002 8136 8831**

Dear Mr. Lado,

SECOND NOTICE OF VIOLATION

An evaluation of the above-referenced property on **07/27/2015** revealed that the structure remains non-compliant with the Housing Code of the City of Portland.

Attached is a list of the violations.

This is a **SECOND** notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected. A re-inspection will occur on **08/26/2015**, at which time compliance will be required.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A M.R.S.A ss 4452.

Please feel free to contact me if you wish to discuss this matter further or have any questions.

Sincerely,

A handwritten signature in black ink, appearing to read "Chuck Fagone".

Chuck Fagone
Code Enforcement Officer
(207) 874-8789

CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager LODOKA LADO		Inspector Chuck Fagone	Inspection Date 6/23/2015
Location 3 HORTON PL	CBL 055 E024001	Status Failed	Inspection Type Complaint-Infestation/Insects

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
------	---------	-------	----------	------	-----------------

1) 6-108. (b) Interior Stairways

Violation: INTERIOR FLOORS, WALLS, CEILINGS AND DOORS

Every floor, wall, ceiling, and door shall be in a structurally sound condition and in good repair and shall be substantially vermin proof.

Notes: *The ceiling in the hallway has partially collapsed and will need to be fixed. The stairway is also missing balusters.*

2) 6-116. (e) Interior Smoke Alarms

Violation: FIRE PROTECTION

Every dwelling, dwelling unit, rooming house and rooming unit shall comply with the applicable provisions of the most current edition of the National Fire Protection Association Life Safety Code, and with all other applicable state statutes and regulations.

Notes: *Smoke detectors are missing in units 2 and 3. Every bedroom should have a photo electric smoke detector and one combination photo electric carbon monoxide detector should be in place in a common area in each unit.*

3) 6-34. (b) Interior Hallway

Violation: ELECTRICAL

Notes: *A junction box in the front hallway is missing a cover.*


Portland, Maine



Yes. Life's good here.

Planning & Urban Development
Inspection Division
389 Congress Street, Room 315
Portland, Maine 04101-3509

PRESORTED
FIRST CLASS



02 1M
0004288097 JUL 28 2015
MAILED FROM ZIP CODE 04105

\$ 00.39¹

699

(1)TF

X 015 NFE 1 614F0008/10/15
FORWARD TIME EXP RTN TO SEND
LODOKA LADO
2820 TERRACE PL APT 6
GARDEN CITY KS 67846-7370

RETURN TO SENDER

04101@3597

