Inspections Division
Date: 08/20/14

168 Clark street
Original layout of second floor before water damage. Demolition was done by Servpro on exterior walls approximately 3 feet from floor. Plaster and lads. Kitchen,bathroom and bedroom.All flooring in this diagram was removed to subfloor. Removed interior bathroom walls and walls around the pantry. These walls are not load bearing walls.