el

Inspections Division
Date: 08/20/14

108 Clark street
Original layout of
first floor before
water water damage.
Demeolition done by
Servpro on exterior walls
approximately
3 feet from floor.
Plaster and lads
Kitchen, bathroom and
bedroom 1 plaster and
lads was removed from
ceilings.
FLOOR
All flooring in this
diagram was rmoved to
subfloor. Removed
interior bathroom walls
and walls around the
pantry area. Please note
these walls are not load
bearing walls.

N

Main Level