Inspections Division

Date: 08/20/14

168 Clark street 2nd floor new

On exterior walls in bedroom 2 and kitchen 2 installed 2 by 4 walls 16" on center for insulation. Relocated bathroom as shown here and put in walk in closet. Also needs all new wallboard, flooring, molding,etc. Also need to relocate plumbing for bathroom. Note house has knob and tube wiring. Was told by a city electrical inspector that all electrical wiring that was exposed to water damage had to be replaced.