

HOUSING INSPECTION REPORT

LOCATION: 52 Pine Street 56-C-7 WE

NAME: Mrs. Theresa A. Betty

SEE STRUCTURE CITATION:

ISSUING AGENCY: APR. 3, 1984      DATES: June 3, 1984  
CITING CODES: "HOUSING CODES"

ITEMS LISTED BELOW ARE IN VIOLATION OF ARTICLE 7 OF THE MUNICIPAL CODES, AND MUST BE CORRECTED ON OR BEFORE THE EXPIRING DATE.

- \* 1. RIGHT FRONT EXTERIOR - foundation - missing bricks and mortar. 108-2
- 2. LEFT REAR & RIGHT REAR EXTERIOR - roof - broken moldings. 108-1
- 3. FIRST FLOOR FRONT HALL - floor - rotting board. 108-2
- 4. CELLAR - flue - extensive chimney work. 114-1
- 5. CELLAR - chimney - missing bricks. 114-1
- \* 6. LEFT FRONT & RIGHT FRONT EXTERIOR - missing bricks & mortar. 108-2

FIRST FLOOR

- 7. KITCHEN - window - missing counterbalancing cords. FIRST FLOOR 108-3
- 8. LIVING ROOM - wall - missing ceiling cement. 113-5

SECOND FLOOR

- 9. KITCHEN - sink - imperative drain. 111-1

\*WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.