



Condition of existing stairs:
 ROTTING WOOD!

Detail and
 Elevation of Existing Deck + Egress Stairs
 @ 46 Eushman St. Portland, Me.

Scale = $\frac{1}{4}'' = 1'-0''$

Contractor: Matt Alcorn LLC
 671-5325
 owner: Mark LeClere
 615-9060