RESURGAM
CITY OF PORTLAND, MAINE
Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 06/10/13

Picture of existing landing and handrail showing the notching back into the front entry woodwork. The existing handrail is only 30” above the landing and on average only 30” above each leading edge of the steps.