



## City of Portland Inspection Violations

<b>Case Number:</b>	RR1800043	<b>Case Module:</b>	Permit Management
<b>Inspection Date:</b>	03/26/2018	<b>Inspection Status:</b>	In Violation
<b>Inspector:</b>	Donald Brown	<b>Inspection Type:</b>	FP Routine Fire Inspection
<b>Job Address:</b>	277 Spring St Portland, ME 04102	<b>Parcel Number:</b>	056 G017001

Contact Type	Company Name	Name
--------------	--------------	------

Checklist Item	Passed	Comments
None		

### Noncompliance

Code Name	Comments	Deadline
NFPA 101-31.3.2 Boiler or Fuel-Fired Heater Protection Boiler and fuel-fired heaters serving more than one dwelling unit must have 1-hour separation or sprinkler protection.	This was noted on a previous inspection. A failed re-inspection fee will be assessed if the deadline for completion is missed.	05/18/2018