CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager POMROY BETTY A			•	Inspector Marland Wing Status			Inspection Date 6/16/2005 Inspection Type	
Locatation CBL 268 SPRING ST 056 1012001								
		056 1012001	Re-Insp	Re-Inspect 30 Days			Complaint-Inspection	
Code	Int/Ext			Floor	Unit No.	Area	Compliance Date	
1) 6-108.1 Violation:	Exterior Foundations	cellars, exterior v	valls roofs	Various locations				
Notes:	Left rear wall missing & Broken clapboards							
2) 6-108.1	Exterior						Various locations	
Violation:	Foundations cellars, exterior walls, roofs							
Notes:	Overall trim peeling paint							
3) 6-108.1	Exterior							
Violation:	Foundations cellars, exterior walls, roofs							
Notes:	Roof rotted b	oards						

Comments: