

56-A-13

SURVEY AND INVESTIGATION OF TENEMENT AND LODGING HOUSES
QUESTIONABLE AS TO LEGAL AND SAFE USE

- 1. Location 39th Bushman St Date investigation commenced 3/12/46
- 2. References: Complaints C-41-134 Appl. BP ✓ Inq. ✓
- 3. Present Owner and Address Grace L. Moody, So. Windham, Me.
- 4. Present Lessee and Address Mrs. Lura T. Moffett - 39 Bushman St
- 5. Building Permit Record: 31/1678 Permit

Assessors' Record

- 6. Survey 1924: Owner Grace L. Moody :No. tenants Seven
No. rooms 9; Class of Use Single tenement
- 7. Assessors' change record since 1924 1925 Single house - 9/31 Court order
9-3-44 - 1.W.C. - 12av.
- 8. Change of Owners, 1924 to date 1921 Grace L. Moody
1936 Grace L. Moody N.R.

9. City Directory Record

1926	<u>S. L. Roy Moody (Grace L.)</u>	1936	<u>Vacant</u>
1927	<u>Same</u>	1937	<u>David P. ...</u>
1928	<u>Same</u>	1938	<u>Vacant</u>
1929	<u>Same</u>	1939	<u>Henry P. Wellman (Alice K.)</u>
1930	<u>Same</u>	1940	<u>Same</u> <u>Henry P. (Alice) Lodge 122 Emery h. do</u>
1931	<u>Same</u>	1941	<u>Same</u> <u>Henry P. Wellman - Alice - 122 Emery</u>
1932	<u>Same</u>	1942	<u>Mrs. Lura M. Moffett</u>
1933	<u>Same</u>	1943	<u>Same</u>
1934	<u>Same</u>	1944	<u>Same</u>
1935	<u>Same</u>	1945	<u>Mrs. Lura Moffett</u>

10. Miscellaneous

1945 Henry P. Wellman (Alice K.) Lodge 122 Emery h. do
C-41-134 - bit bumper in basement blows down when splitting

Conclusions and Action

Copy

56-7-13

INQUIRY BLANK

ZONE _____

FIRE DIST. _____

CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION

Verbal
By Telephone

DATE 3/12/46

LOCATION 39 Cushman St

OWNER Grace S. Hardy - So. Windham

MADE BY Paul State Dept. Health & Welfare

TEL. _____

ADDRESS _____

PRESENT USE OF BUILDING _____

CLASS OF CONSTRUCTION _____

NO. OF STORIES _____

REMARKS: _____

INQUIRY: What is the status of this building?

ANSWER: From records in office this building has always been a single family and still remains the same.

See also letter to State Health & Welfare Dept. - dated 3/19/46

DATE OF REPLY 3/13/46

REPLY BY Paul

December 27, 1941.

Mrs. Grace L. Moody,
South Windham, Me.

Dear Madam:

Re: Oil Burner Installation at 39 Cushman Street, Portland, Me.

At your request, through our Mr. Burwood, the writer today with one of our service men went to 39 Cushman Street and thoroughly checked over your oil burner and have to report the following:

The entire set of Air Baffle Rings is broken and burned, and should be replaced. The set would cost you \$10.00.

When we found it, the Pilot Light was "hovering" - down close to top of Pilot Shield, and all over the top of it. When the fire started, it would puff hard, and smoke would come out around the fire door and air slide. We cleaned out the scale from in top of the Pilot and that helped a little, but the Pilot Light was still too short and the start too heavy. We then took the Pilot Light Control apart, cleaned the orifice of the Pilot Light Nozzle, cleaned the rods of the Control, but it together, turned the Pilot Light up to a height equal to that of the Nozzle of the Burner where it should be, and the start was smooth as possible with this type of burner, and there was no more puff of smoke from the door of the boiler.

We checked the Pilot Light Control, which is designed to turn off the motor of the burner in case the Pilot Light fails, and found it working. However, as you know, this burner is now getting old, and our experience with other burners of similar age indicates that you may expect any time now that the action of this Control will become erratic and unreliable.

To replace the Pilot Light Control, in case it fails to operate properly, with new Controls of modern design that will prevent operation of the burner unless there is a fire started properly, would cost \$30.00 on today's basis. This price, of course, is not firm for the future, but subject to change according to changes in our costs.

C
O
P
Y

Your tenant says she cleans the nozzle frequently, and it's condition indicated it had been cleaned within the last few days.

We cautioned her about seeing that the Pilot Light was maintained at the height equal to the Nozzle, and she said she would watch it. Of course, she cannot clean the Pilot from time to time as is necessary to keep the boiler scale out of the top, and the corrosion out of the orifice.

We found the water too high in the gauge glass for good and economical steaming. Your tenant said she was unable to tell exactly where the water line was because of rust on the outside due to a bad leak at the top of the glass, but that she tried to keep the water a little over half way up in the glass. We found that the upper end of the gauge glass does leak water and steam badly, and this should be taken care of before the water leaves the boiler some day.

From the appearance of the old damper regulator, it also leaks whenever there is pressure on the boiler.

Your tenant said she is using considerably more oil this year than she did during similar periods last year. We found bad air leaks around the boiler clean-out door, and between the frames of the clean-out door and fire door; also under the covering, indicating that the boiler should be re-sealed between the sections, and it also should be re-covered for fuel economy.

A Draft Control on the smoke pipe would undoubtedly reduce fuel consumption, perhaps as much as 10%. A Draft Control of the proper size, installed, would cost you \$10.50.

The leaking gauge glass, and the air leaks described, all contribute to excessive fuel consumption, and if those items are corrected, and if a Draft Control were installed, there should be a considerable reduction in fuel used for the same heating results.

We trust this report gives you the information desired, and are sending a copy to the Department of Building Inspection, City of Portland, for their information also.

If we can be of further service to you in this matter, please call upon us.

Yours very truly,
Ballard Oil & Equipment Company of Maine,

Manager - Oil Burner Division

RDBarstow/B

C
O
P
Y

C-41-131-1

12-23-41-H
Reg. Mail

December 15, 1941

Subject: Dangerous oil burner installation at 23-41 Gushwa Street

Grace L. Moody,
South Windham,
Maine

Dear Madam:

The oil burner installation in the building which you are reported to own at 23-41 Gushwa Street is apparently defective to such an extent as to be positively dangerous, the special trouble being that frequently when the automatic ignition lights the burner the heater doors are blown open, leading to the belief that there is a dangerous defect in the safety devices.

As authorized by Sections 23, 23, 23 and 23 of Chapter 36, Revised Statutes of Maine, copy attached hereto, you are hereby directed to have this dangerous condition permanently corrected not later than December 27, 1941.

We have the opinion of an oil burner expert that the only remedy is the replacement of the burner with a safe one, or perhaps a complete replacement of the safety devices would serve the purpose. Apparently the burner is quite an old installation as we have no record of a permit to cover installation of it. Under these circumstances I should think the replacement of the safeties only at considerable expense taken together with the fact that you would still have an old burner, would make the entire replacement of the oil burning equipment the most attractive course.

Very truly yours,

RCD/H

Inspector of Buildings

MENT HOUSE ZON
Complaint No. C-41-134

Location 39-41 Cushman St.

Date Received 12/6/41

Date Disposed of 7-14-49

NOTES

12/19/41 We have received
of the furnace, evidently
installed before ^{permitted} it.
Tenant has had more or
less trouble with it in
the past and owner will
not do anything. Ballard
Pil had the service calls
last spring. Mr. Boston
of Ballard Pil, explained
the probable safety to
take care of ignition
failure, etc. The reason
it does not operate
probably is due to his
opinion the burner should
be replaced or at least
provided with a new
set of valves, I visited
the job and talked with
the man, she said the
furnace does not blow
off an almost average

ignition, etc.
12/19/41 Mr. Boston of
Ballard Pil called, the
number as talked with
him and said he has
tried to run out and it
operates satisfactory due
to his opinion. The tenant
lowered the gas pilot
flame, pilot setting
proper ignition. The
owner has authorized
Ballard Pil to send a
competent man to check
the burner and report
actual condition, a copy
to be sent to this office.

12/19/41 Mr. Boston of
Ballard Pil called, the
number as talked with
him and said he has
tried to run out and it
operates satisfactory due
to his opinion. The tenant
lowered the gas pilot
flame, pilot setting
proper ignition. The
owner has authorized
Ballard Pil to send a
competent man to check
the burner and report
actual condition, a copy
to be sent to this office.

Al.

FORM 3851
MAY 1 1964

RETURN RECEIPT

From the Postmaster the Registered or Insured Article, the original
number of which appears on the face of this Card.

1. Glenn E. Smith
(Signature of name of addressee)

2. Glenn E. Smith
(Signature of addressee if known. Agent should place address & name on Box ONE, too)

Date of delivery 11/19/64

POSTMASTER'S OFFICE

930124

Permit # _____ City of Portland BUILDING PERMIT APPLICATION Fee \$30 Zone _____ Map # _____ Lot# _____
Please fill out any part which applies to job. Proper plans must accompany form.

Owner: Laura Fauce Phone # 971-0509
Address: 39 Cushman St. #1d, ME 04102
LOCATION OF CONSTRUCTION: 39 Cushman St. - 3rd floor
Contractor: Keith Stiffler Sub: 892-0163
Address: 61 Nash Rd- Windham, ME Phone # 04062
Est. Construction Cost: 2000 Proposed Use: 1-fam w RENOV
Past Use: 1-fam
of Existing Res. Units _____ # of New Res. Units _____
Building Dimensions L _____ W _____ Total Sq. Ft. _____
Stories _____ # Bedrooms _____ Lot Size: _____
Is Proposed Use: Seasonal _____ Condominium _____ Conversion _____
Explain Conversion Interior renovations - 3rd floor

For Official Use Only
Date 2/27/93 Subdivision _____
Name FEB 27 1993
Inside Fire Limits _____
Rdy Code _____
Time Limit _____
Ownership: CITY Public _____ Private LAN
Estimated Cost 2000
Zoning: Street Frontage Provided: _____
Provided Setbacks: Front _____ Back _____ Side _____
Review Required: Zoning Board Approval: Yes _____ No _____ Date: _____
Planning Board Approval: Yes _____ No _____ Date: _____
Conditional Use: _____ Variance _____ Site Plan _____ Subdivision _____
Shoreland Zoning: Yes _____ No _____ Floodplain Yes _____ No _____
Special Exception _____
Other 100-18-93 (Explain)

Foundation:
1. Type of Soil: _____
2. Set Backs - Front _____ Rear _____ Side(s) _____
3. Footings Size: _____
4. Foundation Size: _____
5. Other _____

Floor:
1. Sills Size: _____ Sills must be anchored.
2. Girder Size: _____
3. Lally Column Spacing: _____ Size: _____
4. Joists Size: _____ Spacing 16" O.C.
5. Bridging Type: _____ Size: _____
6. Floor Sheathing Type: _____ Size: _____
7. Other Material: _____

Exterior Walls:
1. Studding Size _____ Spacing _____
2. No. windows _____
3. No. Doors _____
4. Header Sizes _____ Span(s) _____
5. Bracing: Yes _____ No _____
6. Corner Posts Size _____
7. Insulation Type _____ Size _____
8. Sheathing Type: _____ Size _____
9. Siding Type _____ Weather Exposure _____
10. Masonry Materials _____
11. Metal Materials _____

Interior Walls:
1. Studding Size _____ Spacing _____
2. Header Sizes _____ Span(s) _____
3. Wall Covering Type _____
4. Fire Wall if required _____
5. Other Materials _____


Ceiling:
1. Ceiling Joist Size: _____
2. Ceiling Lapping Size _____ Spacing _____
3. Type Ceilings: _____
4. Insulation Type _____ Size _____
5. Ceiling Height: _____
Roof:
1. Truss or Raftar Size _____ Spacing _____
2. Sheathing Type: _____ Size _____
3. Roof Covering _____
Chimneys:
Type: _____ Number of Fire Places _____
Heating:
Type of Heat: _____
Electrical:
Service Entrance Size: _____ Smoke Detector Required Yes _____ No _____
Plumbing:
1. Approval of soil test if required Yes _____ No _____
2. No. of Tubs or Showers _____
3. No. of Fluthes _____
4. No. of Lavatories _____
5. No. of Other Fixtures _____
Swimming Pools:
1. Type: _____
2. Pool Size: _____
3. Must conform to National Electrical Code _____

Permit Returned to Applicant _____
Signature of Applicant: Edward Roy Date 1/1/93
Signature of CEO: _____ Date _____
Inspection Dates _____
PERMIT ISSUED WITH LETTER
PERMIT ISSUED WITH LETTER
Date 1/1/93

PLOT PLAN

3/1/93

Completed OK per plan



FEES (Breakdown From Front)	Type	Inspection Record	Date
Base Fee \$ 30 -			/ /
Subdivision Fee \$			/ /
Site Plan Review Fee \$			/ /
Other Fees \$			/ /
(Explain)			/ /
Late Fee \$			/ /

COMMENTS

Signature of Applicant E. M.

Date 2/10/93 877-0914

Inspection Services
Samuel P. Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

February 19, 1993

Laura Faure
39 Cushman St
Portland, ME 04103

Re: 39 Cushman St

Dear Ms. Faure,


Your application to make interior renovations (3rd floor) has been reviewed and a permit is herewith issued subject to the following requirements:

No certificate of occupancy can be issued until all requirements of this letter are met.

1. This permit is being issued with the understanding that no additional dwelling unit is created.
2. Please read and implement items numbered 6, 7, 9, 12, 13, 14, and 15 of the attached building permit report.

If you have any questions regarding these requirements, please do not hesitate to contact this office.

Sincerely,


S. Samuel Hoffses
Chief of Inspection Services

BUILDING PERMIT REPORT

ADDRESS: 39 Johnson ST 3rd Fl. DATE: 14 Feb 1993

REASON FOR PERMIT: To MAKE INTERIOR RENOVATION
3rd Floor

BUILDING OWNER: Fairl

CONTRACTOR: Meith Staff

PERMIT APPLICANT: 11

APPROVED: *6 *7 *9 *12 *13 *14 *15


CONDITION OF APPROVAL:

- 1.) Before concrete for foundation is placed, approvals from Public Works and Inspection Services must be obtained. (A 24 hour notice is required prior to inspection.)
- 2.) Precaution must be taken to protect concrete from freezing.
- 3.) All vertical openings shall be enclosed with construction having a fire rating of at least one(1) hour, including fire doors with self-closers.
- 4.) Each apartment shall have access to two(2) separate, remote and approved means of egress. A single exit is acceptable when it exits directly from the apartment to the building exterior with no communications to other apartment units.
- 5.) The boiler shall be protected by enclosing with one(1) hour fire rated construction including fire doors and ceiling, or by providing automatic extinguishment. Sprinkler piping serving not more than six sprinklers may be connected to a domestic water supply system having a capacity sufficient to provide 0.15 gallons per minute, per square foot of floor throughout the entire area. An INDICATING shut-off valve shall be installed in an accessible location between the sprinkler and the connection to the domestic water supply. Minimum pipe size shall be 3/4 inch copper or 1 inch steel. Maximum coverage area of a residential sprinkler is 144 square feet per sprinkler.
- 6.) Every sleeping room below the fourth story in buildings of Use Groups I and I-1 shall have at least one operable window or exterior door approved for emergency egress or rescue. The unit must be operable from the inside opening without the use of separate tools. Where windows are provided as a means of egress or rescue, they shall have a sill height not more than 44 inches (1118 mm) above the floor. All egress or rescue windows from sleeping rooms must have minimum net clear openings of 5.7 square feet (0.53m²). The minimum net clear opening height dimension shall be 24 inches (610 mm). The minimum net clear opening width dimension shall be 20 inches (508 mm).
- 7.) All single and multiple-station smoke detectors shall be of approved type and shall be installed in accordance with 101 of the building code (BOCA National Building Code 1990 101 Chapter 18 & 19).

(over)

- 8.) Private garages located beneath rooms in buildings of Use Groups R-1, R-2, R-3 or I-1 shall have walls, partitions, floors and ceilings separating the garage space from the adjacent interior spaces constructed of not less than 1-hour fireresistance rating. Attached private garages shall be completely separated from the adjacent interior spaces and the attic area by means of 1/2-inch gypsum board or equivalent applied to the garage side. The sills of all door openings between the garage and adjacent interior spaces shall be raised not less than 4 inches (102 mm) above the garage floor. The door opening protectives shall be 1 3/4-inch solid core wood doors or approved equivalent.
- X 9.) A guardrail system located near the open side of deck or elevated walking surfaces shall be constructed. Guards in buildings of Use Group R-3 shall be not less than 36 inches in height. Open guards shall have intermediate rails, balusters or other construction such that a sphere with a diameter of 4 inches cannot pass through any opening. Handrails on stairs shall be no less than 34 inches nor more than 38 inches. Handrails in individual dwelling units shall not be less than 30 inches nor more than 38 inches. For more detail on guards & handrails see Article 8 section 824.0 and 825.0 of the National Building Code.
- 10.) Section 25-135 of the Municipal Code for the City of Portland states: "No person or utility shall be granted a permit to excavate or open any street or sidewalk from the time of November 15 of each year to April 15 of the following year.
- 11.) The builder of a facility to which Section 4594-C of the Maine State Human Rights Act, Title 5 M.R.S.A. refers, shall obtain a certification from a design professional that the plans of the facility meet the standards of construction required by this section. Prior to commencing construction of the facility, the builder shall submit the certification to the Division of Inspection Services.
- X 12.) Stair construction in Use Group R-3, R-4, is a minimum of 9" tread and 8-1/4" maximum rise.
- X 13.) Headroom in habitable spaces is a minimum of 7'6".
- X 14.) The minimum headroom in all parts of a stairway shall not be less than 6 feet 8 inches.
- X 15.) All construction and demolition debris must be disposed at the RWS by a licensed carrier or solid waste at the City's authorized reclamation site. The fee rate is attached. Proof of such disposal must be furnished to the office of Inspection Services before final certificate of occupancy is issued or demolition permit is granted.

Sincerely,


P. Samuel Hoffses
Chief of Inspection Services

/el

11/16/88-11/27/90-8/14/91-9/2/92-10/14/92

DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME

R FEB 10 1993 D
RECEIVED

BUILDER: KEITH STIFFLER
61 NASH RD.
WINDHAM, ME. 04062
892-0164

2-8-93


OWNER: LAURA FAURE
39 CUSHMAN ST.
PORTLAND, ME. 04103
871-0509

SCOPE OF WORK

THE AREA AS SHOWN ON THE PLAN IS AS SHOWN. ALL OPEN. WE
INTEND TO DO THE WORK AS NOTED.

INSTALL A NEW KNEE WALL AT 32"
INSTALL COLLAR TIES
BUILD 2 NEW PARTITIONS AS NOTED 2x4 16' OC
INSTALL NEW SUB-FLOOR OVER THE ENTIRE AREA
1X3 STRAPPING ON ALL SLOPE AND FLAT CEILINGS
INSULATE TOTAL AREA

THE CONTRACTOR IS FINISHING ONLY THE SPACE AS IT EXISTS NOW.
THERE ARE NO STRUCTURAL CHANGES.



KEITH R. STIFFLER


DEPT. OF BUILDING INSPECTION
CITY OF PORTLAND, ME

R FEB 10 1993 **D**
RECEIVED

BUILDER: KEITH STIFFLER
61 NASH RD.
WINDHAM, ME. 04062
892-0114

2-8-93

OWNER: LAURA FAURE
39 CUSHMAN ST.
PORTLAND, ME. 04103
871-0509



930124

Permit # _____ City of Portland BUILDING PERMIT APPLICATION Fee \$30 Zone _____ Map # _____ Lot# _____

Please fill out any part which applies to job. Proper plans must accompany form.

Officer: Laura Faure Phone # 871-0509
 Address: 39 Cushman St. Ptld, ME 04103
 LOCATION OF CONSTRUCTION 39 Cushman St. - 3rd floor
 Contractor: Keith Stiffler Sub: 892-0164
 Address: 61 Nash Rd- Windham, ME Phone # 04062
 Est. Construction Cost: 2000 Proposed Use: 1-fam w renov
 Past Use: 1-fam
 # of Existing Res. Units _____ # of New Res. Units _____
 Building Dimensions L _____ W _____ Total Sq. Ft. _____
 # Stories: _____ # Bedrooms _____ Lot Size: _____
 Is Proposed Use: Seasonal _____ Condominium _____ Conversion _____
 Explain Conversion Interior renovations - 3rd floor

For Official Use Only

Date 2/10/93 Subdivision: _____
 Inside Fire Limits _____ Name FEB 22 1993
 Bldg Code _____ Lot _____
 Time Limit _____ Ownership: City of Portland Public _____ Private _____
 Estimated Cost: 2000

Zoning:
 Street Frontage Provided: _____
 Provided Setbacks: Front _____ Back _____ Side _____ Side _____

Review Required:
 Zoning Board Approval: Yes _____ No _____ Date: _____
 Planning Board Approval: Yes _____ No _____ Date: _____
 Conditional Use: _____ Variance _____ Site Plan _____ Subdivision _____
 Shoreland Zoning Yes _____ No _____ Floodplain Yes _____ No _____
 Special Exception _____
 Other: WDA 2-18-93 (Explain)

Foundation:

- Type of Soil: _____
- Set Backs - Front _____ Rear _____ Side(s) _____
- Footings Size: _____
- Foundation Size: _____
- Other: _____

Floor:

- Sills Size: _____ Sills must be anchored.
- Girder Size: _____
- Lally Column Spacing: _____ Size: _____
- Joists Size: _____ Spacing 16" O.C.
- Bridging Type: _____ Size: _____
- Floor Sheathing Type: _____ Size: _____
- Other Material: _____

Exterior Walls:

- Studding Size _____ Spacing _____
- No. windows _____
- No. Doors _____
- Header Sizes _____ Span(s) _____
- Bracing: Yes _____ No _____
- Corner Posts Size _____
- Insulation Type _____ Size _____
- Sheathing Type _____ Size _____
- Siding Type _____ Weather Exposure _____
- Masonry Materials _____
- Metal Materials _____

Interior Walls:

- Stud ling Size _____ Spacing _____
- Header Sizes _____ Span(s) _____
- Wall Covering Type _____
- Fire Wall if required _____
- Other Materials _____

Ceiling:

- Trussing Joists Size: _____ **HISTORIC PRESERVATION**
- Trussing Strapping Size _____ Spacing _____
- Type Ceilings: _____ Not in District nor Landmark
- Insulation Type _____ size _____ Does not require review
- Ceiling Height: _____ Requires Review

Roof:

- Truss or Rafter Size _____ Span _____
- Sheathing Type _____ Size _____ Approved
- Roof Covering Type _____ Approved with Conditions

Chimneys:
 Type: _____ Number of Fire Places _____ Date: 2/10/93
 Signature: [Signature]

Heating:
 Type of Heat: _____

Electrical:
 Service Entrance Size: _____ Smoke Detector Required Yes _____ No _____

Plumbing:

- Approval of soil test if required Yes _____ No _____
- No. of Tubs or Showers _____
- No. of Flushes _____
- No. of Lavatories _____
- No. of Other Fixtures _____

Swimming Pools:

- Type: _____
- Pool Size: _____
- Must conform to National Electrical Code and State Law.


Permit Received By Louise E. Chase
 Signature of Applicant [Signature] Date 2/10/93
 Signature of CEO Edward Roy Date _____

Inspection Dates _____

White-Tax Assessor Yellow-GPCOC White Tag-CEO

© Copyright GPCOG 1938

37 MRS. Lowry





APPLICATION FOR PERMIT
DEPARTMENT OF BUILDING INSPECTIONS SERVICES
ELECTRICAL INSTALLATIONS

Date February 11, 1993 19
 Receipt and Permit number 14174

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 39 Cushman St
 OWNER'S NAME: Laura Faure ADDRESS: _____

	FEES
OUTLETS:	
Receptacles <u>12</u> Switches <u>3</u> Plugmold _____ ft. TOTAL _____	3.00
FIXTURES: (number of)	
Incandescent <u>2</u> Fluorescent _____ (not strip) TOTAL _____	.40
Strip Fluorescent _____ ft. _____	
SERVICES:	
Overhead _____ Underground _____ Temp _____ TOTAL amperes _____	
METERS: (number of) _____	
MOTORS: (number of)	
Fractional _____	
1 HP or over _____	
RESIDENTIAL HEATING:	
Oil or Gas (number of units) _____	
Electric (number of rooms) _____	
COMMERCIAL OR INDUSTRIAL HEATING:	
Oil or Gas (by a main boiler) _____	
Oil or Gas (by separate units) _____	
Electric Under 20 kws _____ Over 20 kws _____	
APPLIANCES: (number of)	
Ranges _____	Water Heaters _____
Cook Tops _____	Disposals _____
Wall Ovens _____	Dishwashers _____
Dryers _____	Compactors _____
Fans _____	Others (denote) _____
TOTAL _____	
MISCELLANEOUS: (number of)	
Branch Panels _____	
Transformers _____	
Air Conditioners Central Unit _____	
Separate Units (windows) _____	
Signs 20 sq. ft. and under _____	
Over 20 sq. ft. _____	
Swimming Pools Above Ground _____	
In Ground _____	
Fire/Burglar Alarms Residential _____	
Commercial _____	
Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under _____	
over 30 amps _____	
Circus, Fairs, etc. _____	
Alterations to wires _____	
Repairs after fire _____	
Emergency Lights, battery _____	
Emergency Generators _____	
	INSTALLATION FEE DUE: _____
	FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT DOUBLE FEE DUE: _____
	FOR REMOVAL OF A "STOP ORDER" (304-16.b) _____
	TOTAL AMOUNT DUE: <u>15.00</u>

INSPECTION:

Will be ready on 2/12/AM, 19 ; or Will Call _____
 CONTRACTOR'S NAME: Ronald Laughton
 ADDRESS: P.O. Box 1297 Scarborough 04070
 TEL.: 883-5858
 MASTER LICENSE NO.: 14174 SIGNATURE OF CONTRACTOR: _____
 LIMITED LICENSE NO.: _____

INSPECTOR'S COPY — WHITE
 OFFICE COPY — CANARY
 CONTRACTOR'S COPY — GREEN

