CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager LOURIE RAYMOND H		Inspector	Inspection Date
		Marland Wing	5/24/2005
Locatation	CBL	Status	Inspection Type
254 SPRING ST	057 C002001	Re-Inspect 30 Days	Complaint-Inspection

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1)	6-108.1 Exterior Violation: Foundations cellars, exterior walls, roofs Notes: Rear Wall Loose Siding		3	Various locations		cations
2)	6-108.1 Exterior Violation: Foundations cellars, exterior walls, roofs Notes: Front Wall Missing Shingle		3		Various locations	

Comments: