CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
GRAFF ROBERT E		Suzanne Hunt	5/9/2007
Locatation	CBL	Status	Inspection Type
112 CLARK ST	057 C010001	Re-Inspect 10 Days	Complaint-Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 6-111.1 Exterior

Violation: Plumbing standards/Basic facilities.

Notes: Water cannot be pumped from house unto city public way. IRC 2003 401.3 drainage shall be diverted

to an approved point of collection.

Comments: hose coming out of front window of cellar is either a sump pump or a wash machine hose. This hose

must be re directed to insure that water is not crossing the sidewalk.