

Compliance Date:

Code	Int/Ext	Status/Date	Notes:	Unit No.	Floor	Area	Compliant/Compliance Date
------	---------	-------------	--------	----------	-------	------	---------------------------

ScheduleID: 
 ViolationID:

6-108.1	Exterior					Various locations	<input type="checkbox"/>		Violation Date 12/18/2006
Open	roof must be made weathertight.								
6-108.1	Exterior					Various locations	<input type="checkbox"/>		Violation Date 12/18/2006
Open	windows must be repaired to good repair and sound working conditions								
6-108.1	Exterior					Various locations	<input type="checkbox"/>		Violation Date 12/18/2006
Open	exterior walls must be made to be substantially weathertight								
6-108.1	Exterior					Various locations	<input type="checkbox"/>		Violation Date 12/18/2006
Open	exterior walls must be made structurally sound								
6-108.1	Exterior					Various locations	<input type="checkbox"/>		Violation Date 12/18/2006
Open	roof and exterior walls must be made to be vermin proof.								
6-108.1	Exterior					Various locations	<input type="checkbox"/>		Violation Date 12/18/2006
Open	roof must be repaired to be structurally sound								

Create By: 
 Create Date: