

SimplexGrinnell

FIRE ALARM INSPECTION REPORT

**Performed in Accordance with Applicable
National Fire Protection Association Standards**

March 2019 Inspection

PREPARED FOR

**Cynde Dunn
Manager
Danforth Heights
48 Salem Street
Portland, ME 04102
(207) 772-4386**

03/29/2019

SimplexGrinnell

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

TABLE OF CONTENTS

Test Summary	1
Monitoring/Jurisdictional Agencies	3
Test Results - Control Panel/Central Processing Unit	4
Test Results - Alarm Initiating Devices	7
Test Results - Alarm Indicating Devices	12
Test Results - Supervisory Devices	20
Test Results - Control/Auxiliary Devices	21
Sensitivity Test Results	22
Inspection Deficiencies Summary	25
Inspection Deficiencies	26

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

PAGE 1

**Cynde Dunn
Manager
Danforth Heights
48 Salem Street
Portland, ME 04102**

Thank you for choosing SimplexGrinnell as the provider of your Fire Alarm Inspection services, which began on March 11, 2019, and were completed on March 29, 2019.

SIMPLEXGRINNELL PERFORMED THE ANNUAL TEST AND INSPECTION OF THE FIRE ALARM SYSTEMS IN THE BUILDINGS FOR THE DANFORTH HEIGHTS APARTMENT COMPLEX.

THE FOLLOWING TESTS WERE PERFORMED:

240 DANFORTH STREET (BUILDING "A"): MANUAL PULL STATIONS, SMOKE DETECTORS, AND HEAT DETECTORS WERE TESTED FOR ALARM INITIATION. SMOKE DETECTORS WERE CLEANED. FIXED TEMPERATURE TYPE HEAT DETECTOR WAS ELECTRICALLY TESTED.

AUDIO-VISUAL DEVICES WERE SOUNDED BUILDING WIDE.

TEST SIGNALS FOR ALARM AND TROUBLE CONDITIONS WERE SENT TO AND RECEIVED BY PROTECTION ONE'S CENTRAL STATION.

GENERAL ALARM TEST SIGNAL SENT TO AND RECEIVED BY PORTLAND FIRE DEPARTMENT VIA AES RADIO BOX.

21 SCHOOL STREET (BUILDING "B"):

ON ARRIVAL AND DEPARTURE, DIALER REPORTED TROUBLE CONDITION DUE TO NO VOLTAGE ON PHONE LINE TWO (PREVIOUS NUMBER USED WAS 874-0629, NOW DISCONNECTED). FOLLOW UP WITH PHONE SERVICE PROVIDER IS NEEDED TO IDENTIFY AVAILABLE LINE WHICH CAN BE USED AS SECONDARY MEANS OF COMMUNICATION (NOT DEDICATED IS ACCEPTABLE).

MANUAL PULL STATIONS, SMOKE DETECTORS, AND HEAT DETECTORS WERE TESTED FOR ALARM INITIATION. SMOKE DETECTORS WERE CLEANED. FIXED TEMPERATURE HEAT DETECTOR WAS ELECTRICALLY TESTED.

AUDIO-VISUAL UNITS WERE TESTED BUILDING WIDE. APARTMENT 302 HORN WAS INACCESSIBLE (NO KEY).

TEST SIGNALS FOR ALARM AND TROUBLE CONDITIONS WERE SENT TO AND RECEIVED BY PROTECTION ONE.

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

PAGE 2

Danforth Heights

GENERAL ALARM TEST SIGNAL SENT TO AND RECEIVED BY PORTLAND FIRE DEPARTMENT VIA AES RADIO BOX.

48 SALEM STREET (BUILDING "C"): MANUAL PULL STATIONS, HEAT DETECTORS, AND SMOKE DETECTORS WERE TESTED FOR ALARM INITIATION. SMOKE DETECTORS WERE CLEANED.

FIXED TEMPERATURE TYPE HEAT DETECTORS WERE ELECTRICALLY TESTED.

A TEST OF THE VOICE COMMUNICATION SYSTEM WAS PERFORMED (MICROPHONE OVERRIDE OPERATIONAL). AUDIO AND AUDIO-VISUAL DEVICES WERE TESTED BUILDING WIDE. THE AUDIO-VISUAL LOCATED NEAR APARTMENT 308 FAILED VISUALLY AND REQUIRES REPLACEMENT (USE WHEELLOCK SPEAKER VISUAL).

TEST SIGNALS FOR ALARM AND TROUBLE CONDITIONS WERE SENT TO AND RECEIVED BY PROTECTION ONE'S CENTRAL STATION.

GENERAL ALARM TEST SIGNAL SENT TO AND RECEIVED BY PORTLAND FIRE DEPARTMENT VIA AES RADIO BOX.

SMOKE DETECTOR MODEL NUMBER IS CERBERUS PYROTRONICS PE-11.

FIRE FIGHTER PHONE CONTROLLER HANDSET (ATLAS SOUNDOLIER) WAS FOUND TO HAVE A FAULTY CONNECTION AND WAS NON-OPERATIONAL (NO AUDIO) DURING INITIAL TEST. AFTER WIRING WAS TEMPORARILY RELOCATED, HANDSET WAS OPERATIONAL AND PHONE JACKS AND REMOTE HANDSETS WERE SUCCESSFULLY TESTED. AS REPLACEMENT PARTS ARE NO LONGER AVAILABLE FOR THIS PANEL, FIREFIGHTER PHONES NEED TO BE INTEGRATED INTO MAIN FIRE PANEL (SIMPLEX 4100ES). A QUOTE FOR THIS WORK WILL BE SUBMITTED UNDER DEFICIENCY REPAIR.

AS ONE HUNDRED PERCENT OF SMOKE SENSITIVITY TESTING WAS PERFORMED AT 2018 INSPECTION, DETECTORS WILL NEXT BE SENSITIVITY TESTED AT 2020 ANNUAL INSPECTION.

ALL LOCAL SMOKE DETECTORS LOCATED IN APARTMENTS ARE NOT PART OF THE FIRE ALARM SYSTEMS AND WERE NOT TESTED.

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

PAGE 3

SITE: Danforth Heights

Monitoring Agency:

Protection One/Portland F.D.

**Central Station
(877) 357-1808**

Authority Having Jurisdiction:

**Portland Fire Dept.
Portland, ME 04101**

**Dispatch
(207) 874-8576**

Inspection Service:

**SimplexGrinnell
30 Thomas Drive
Westbrook, ME 04092
Phone: (207) 842-6440**

License No.: NICET II 133406

**Service Mgr: Vicky Allen
Service Sales: Ryan Hunt
Inspector: John Linscott
Inspector: Chuck Baickle**

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

PAGE 4

SITE: Danforth Heights

CONTROL PANEL/CENTRAL PROCESSING UNIT

Pyrotronics PXL

Serial #

Building: 21 School Street Floor: Gnd Area: Boiler Room

<u>Test Performed</u>	<u>Result</u>	<u>Value</u>	<u>Notes</u>
Voltage w/ Charger	Passed	27.4	
Voltage w/o Charger	Passed	24.6	
Battery % of Charge	Passed		
Battery Age Check	Passed		
Zone Trouble	Passed		
Signal Trouble	Passed		
Type Signal Circuit	Passed		
AC Input Voltage	Passed	120.0	
Earth Detection	Passed		
Lamps/LED Test	Passed		
Drill Switch	Not Applicable		
Control Function(s)	Passed		

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

CONTROL PANEL/CENTRAL PROCESSING UNIT

Simplex 4007-9101

Serial # H10254

Building: 240 Danforth Street Floor: Gnd Area: Boiler Room

<u>Test Performed</u>	<u>Result</u>	<u>Value</u>	<u>Notes</u>
Voltage w/ Charger	Passed	27.8	
Voltage w/o Charger	Passed	24.9	
Battery % of Charge	Passed		
Battery Age Check	Passed		
Zone Trouble	Passed		
Signal Trouble	Passed		
Type Signal Circuit	Passed		
AC Input Voltage	Passed	120.0	
Earth Detection	Passed		
Lamps/LED Test	Passed		
Drill Switch	Not Applicable		
Control Function(s)	Passed		

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

PAGE 6

SITE: Danforth Heights

CONTROL PANEL/CENTRAL PROCESSING UNIT

Simplex 4100ES

Serial # 00119937

Building: 48 Salem Street Floor: 4th Area: Center Stairwell (FACP)

<u>Test Performed</u>	<u>Result</u>	<u>Value</u>	<u>Notes</u>
Voltage w/ Charger	Passed	27.9	
Voltage w/o Charger	Passed	24.9	
Battery % of Charge	Passed		
Battery Age Check	Passed		
Zone Trouble	Passed		
Signal Trouble	Passed		
Type Signal Circuit	Passed		
AC Input Voltage	Passed	120.0	
Earth Detection	Passed		
Lamps/LED Test	Passed		
Drill Switch	Not Applicable		
Control Function(s)	Passed		

SITE: Danforth Heights

ALARM INITIATING DEVICES

SUMMARY TEST RESULTS

<u>Dev. Type</u>	<u>Description</u>	<u>Total</u>	<u>Number Tested</u>	<u>Number Failed</u>	<u>Number Not Tested</u>
HD	Heat Detector	8	8	0	0
PSD	Photo Smoke Detector	97	97	0	0
PSSA	Pull Station-Single Action	44	44	0	0

DETAIL TEST RESULTS

<u>ev</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust Zone</u>	<u>Cust Dev#</u>	<u>Address/ Zone No.</u>	<u>Service Performed</u>	<u>Test Result</u>
SA	21 School Street	1st	Entry Vestibule near 101	5			Tested	Passed
SA	21 School Street	1st	Entry Vestibule near 111	5			Tested	Passed
SA	21 School Street	1st	Exit near 101	3			Tested	Passed
SA	21 School Street	1st	Exit near 111	3			Tested	Passed
ID	21 School Street	1st	Hallway near 101	4			Tested	Passed
ID	21 School Street	1st	Hallway near 103	4			Tested	Passed
ID	21 School Street	1st	Hallway near 105	4			Tested	Passed
ID	21 School Street	1st	Hallway near 107	4			Tested	Passed
ID	21 School Street	1st	Hallway near 108	4			Tested	Passed
ID	21 School Street	1st	Hallway near 109	4			Tested	Passed
ID	21 School Street	1st	Hallway near 111	4			Tested	Passed
SA	21 School Street	2nd	Exit near 201	5			Tested	Passed
SA	21 School Street	2nd	Exit near 207	5			Tested	Passed
SA	21 School Street	2nd	Exit near 211	5			Tested	Passed
ID	21 School Street	2nd	Hallway near 201	6			Tested	Passed
ID	21 School Street	2nd	Hallway near 203	6			Tested	Passed
ID	21 School Street	2nd	Hallway near 205	6			Tested	Passed
ID	21 School Street	2nd	Hallway near 207	6			Tested	Passed
ID	21 School Street	2nd	Hallway near 208	6			Tested	Passed
ID	21 School Street	2nd	Hallway near 209	6			Tested	Passed
ID	21 School Street	2nd	Hallway near 211	6			Tested	Passed
ID	21 School Street	2nd	Stair near 211	6			Tested	Passed
SA	21 School Street	3rd	Exit near 301	7			Tested	Passed
SA	21 School Street	3rd	Exit near 307	7			Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INITIATING DEVICES

DETAIL TEST RESULTS

<u>ev</u> <u>ype</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust</u> <u>Zone</u>	<u>Cust</u> <u>Dev#</u>	<u>Address/</u> <u>Zone No.</u>	<u>Service</u> <u>Performed</u>	<u>Test</u> <u>Result</u>
SD	21 School Street	3rd	Hallway near 301	8			Tested	Passed
SD	21 School Street	3rd	Hallway near 303	8			Tested	Passed
SD	21 School Street	3rd	Hallway near 305	8			Tested	Passed
SD	21 School Street	3rd	Hallway near 307	8			Tested	Passed
SD	21 School Street	3rd	Hallway near Trash Chute	8			Tested	Passed
SD	21 School Street	3rd	Stair near 301	8			Tested	Passed
SD	21 School Street	3rd	Stairwell near 307	8			Tested	Passed
D	21 School Street	3rd	Top of Trash Chute (FT)	9			Tested	Passed
Electrical Test Only								
SSA	21 School Street	Gnd	Boiler Room	1			Tested	Passed
D	21 School Street	Gnd	Boiler Room	2			Tested	Passed
SSA	21 School Street	Gnd	Exit near 2	1			Tested	Passed
SD	21 School Street	Gnd	Hallway near 2	2			Tested	Passed
SD	21 School Street	Gnd	Hallway near 3	2			Tested	Passed
SD	21 School Street	Gnd	Hallway near 5	2			Tested	Passed
SSA	240 Danforth Street	1st	Exit near Trash Chute	1			Tested	Passed
SD	240 Danforth Street	1st	Hallway near 104	2			Tested	Passed
SD	240 Danforth Street	1st	Hallway near 106	2			Tested	Passed
SD	240 Danforth Street	1st	Hallway near 108	2			Tested	Passed
SD	240 Danforth Street	1st	Hallway near 110	2			Tested	Passed
SD	240 Danforth Street	1st	Hallway near Trash Chute	2			Tested	Passed
SSA	240 Danforth Street	1st	Vestibule near 110	3			Tested	Passed
SSA	240 Danforth Street	1st	Vestibule near Trash Chute	3			Tested	Passed
SSA	240 Danforth Street	2nd	Exit near 210	3			Tested	Passed
SSA	240 Danforth Street	2nd	Exit near Trash Chute	3			Tested	Passed
SD	240 Danforth Street	2nd	Hallway near 204	4			Tested	Passed
SD	240 Danforth Street	2nd	Hallway near 206	4			Tested	Passed
SD	240 Danforth Street	2nd	Hallway near 208	4			Tested	Passed
SD	240 Danforth Street	2nd	Hallway near 210	4			Tested	Passed
SD	240 Danforth Street	2nd	Hallway near Trash Chute	4			Tested	Passed
SSA	240 Danforth Street	3rd	Exit near 310	5			Tested	Passed
SSA	240 Danforth Street	3rd	Exit near Trash Chute	5			Tested	Passed
SD	240 Danforth Street	3rd	Hallway near 304	6			Tested	Passed
SD	240 Danforth Street	3rd	Hallway near 306	6			Tested	Passed
SD	240 Danforth Street	3rd	Hallway near 308	6			Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INITIATING DEVICES

DETAIL TEST RESULTS

<u>Dev</u> <u>Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust</u> <u>Zone</u>	<u>Cust</u> <u>Dev#</u>	<u>Address/</u> <u>Zone No.</u>	<u>Service</u> <u>Performed</u>	<u>Test</u> <u>Result</u>
SD	240 Danforth Street	3rd	Hallway near 310	6			Tested	Passed
SD	240 Danforth Street	3rd	Hallway near Trash Chute	6			Tested	Passed
SD	240 Danforth Street	3rd	Stairwell near 310	6			Tested	Passed
SD	240 Danforth Street	3rd	Stairwell near Trash Chute	6			Tested	Passed
D	240 Danforth Street	3rd	Top of Trash Chute (FT)	9			Tested	Passed
				Electrical Test Only				
SSA	240 Danforth Street	Gnd	Boiler Room	7			Tested	Passed
D	240 Danforth Street	Gnd	Boiler Room	8			Tested	Passed
SD	48 Salem Street	1st	Center Stairwell			M1-1	Tested	Passed
SSA	48 Salem Street	1st	Center Stairwell	2			Tested	Passed
SSA	48 Salem Street	1st	Exit near Apt 103	2			Tested	Passed
SSA	48 Salem Street	1st	Exit near Apt 107	2			Tested	Passed
SD	48 Salem Street	1st	Near Apt 101			M1-1	Tested	Passed
SD	48 Salem Street	1st	Near Apt 102			M1-1	Tested	Passed
SD	48 Salem Street	1st	Near Apt 103			M1-1	Tested	Passed
SD	48 Salem Street	1st	Near Apt 104			M1-1	Tested	Passed
SD	48 Salem Street	1st	Near Apt 105			M1-1	Tested	Passed
SD	48 Salem Street	1st	Near Apt 106			M1-1	Tested	Passed
SD	48 Salem Street	1st	Near Apt 107			M1-1	Tested	Passed
SD	48 Salem Street	2nd	Center Stairwell			M1-2	Tested	Passed
SSA	48 Salem Street	2nd	Center Stairwell	3			Tested	Passed
SSA	48 Salem Street	2nd	Exit near Apt 203	3			Tested	Passed
SSA	48 Salem Street	2nd	Exit near Apt 207	3			Tested	Passed
SD	48 Salem Street	2nd	Near Apt 201			M1-2	Tested	Passed
SD	48 Salem Street	2nd	Near Apt 202			M1-2	Tested	Passed
SD	48 Salem Street	2nd	Near Apt 203			M1-2	Tested	Passed
SD	48 Salem Street	2nd	Near Apt 204			M1-2	Tested	Passed
SD	48 Salem Street	2nd	Near Apt 205			M1-2	Tested	Passed
SD	48 Salem Street	2nd	Near Apt 206			M1-2	Tested	Passed
SD	48 Salem Street	2nd	Near Apt 207			M1-2	Tested	Passed
D	48 Salem Street	3rd	Boiler Room (FT)	9			Tested	Passed
				Electrical Test Only				
SSA	48 Salem Street	3rd	Boiler Room Exit	10			Tested	Passed
SD	48 Salem Street	3rd	Center Stairwell			M1-3	Tested	Passed
SSA	48 Salem Street	3rd	Center Stairwell	4			Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INITIATING DEVICES

DETAIL TEST RESULTS

<u>Dev</u> <u>Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust</u> <u>Zone</u>	<u>Cust</u> <u>Dev#</u>	<u>Address/ Zone No.</u>	<u>Service</u> <u>Performed</u>	<u>Test</u> <u>Result</u>
SSA	48 Salem Street	3rd	Exit near Apt 303	4			Tested	Passed
SSA	48 Salem Street	3rd	Exit near Apt 310	4			Tested	Passed
ID	48 Salem Street	3rd	Foyer by Laundry			M1-3	Tested	Passed
SSA	48 Salem Street	3rd	Management Office Lobby	4			Tested	Passed
SD	48 Salem Street	3rd	Near Apt 301			M1-3	Tested	Passed
SD	48 Salem Street	3rd	Near Apt 302			M1-3	Tested	Passed
SD	48 Salem Street	3rd	Near Apt 303			M1-3	Tested	Passed
SD	48 Salem Street	3rd	Near Apt 306			M1-3	Tested	Passed
SD	48 Salem Street	3rd	Near Apt 308			M1-3	Tested	Passed
SD	48 Salem Street	3rd	Near Apt 310			M1-3	Tested	Passed
SD	48 Salem Street	3rd	Near Boiler Room			M1-3	Tested	Passed
SSA	48 Salem Street	3rd	Stairwell Exit near Apt 303	5			Tested	Passed
SSA	48 Salem Street	3rd	Stairwell Exit near Apt 310	5			Tested	Passed
SD	48 Salem Street	4th	Center Stairwell			M1-4	Tested	Passed
SSA	48 Salem Street	4th	Center Stairwell	5			Tested	Passed
SSA	48 Salem Street	4th	Exit by Apt 405	5			Tested	Passed
SSA	48 Salem Street	4th	Exit by Apt 413	5			Tested	Passed
SSA	48 Salem Street	4th	Main Entry Vestibule	5			Tested	Passed
SD	48 Salem Street	4th	Near Apt 401			M1-4	Tested	Passed
SD	48 Salem Street	4th	Near Apt 403			M1-4	Tested	Passed
SD	48 Salem Street	4th	Near Apt 405			M1-4	Tested	Passed
SD	48 Salem Street	4th	Near Apt 408			M1-4	Tested	Passed
SD	48 Salem Street	4th	Near Apt 410			M1-4	Tested	Passed
SD	48 Salem Street	4th	Near Apt 412			M1-4	Tested	Passed
SD	48 Salem Street	4th	Near Apt 414			M1-4	Tested	Passed
SD	48 Salem Street	5th	Center Stairwell			M1-5	Tested	Passed
SSA	48 Salem Street	5th	Center Stairwell	6			Tested	Passed
SSA	48 Salem Street	5th	Exit near Apt 505	6			Tested	Passed
SSA	48 Salem Street	5th	Exit near Apt 514	6			Tested	Passed
SD	48 Salem Street	5th	Near Apt 501			M1-5	Tested	Passed
SD	48 Salem Street	5th	Near Apt 503			M1-5	Tested	Passed
SD	48 Salem Street	5th	Near Apt 505			M1-5	Tested	Passed
SD	48 Salem Street	5th	Near Apt 508			M1-5	Tested	Passed
SD	48 Salem Street	5th	Near Apt 510			M1-5	Tested	Passed
SD	48 Salem Street	5th	Near Apt 512			M1-5	Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INITIATING DEVICES

DETAIL TEST RESULTS

<u>Dev</u> <u>Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust</u> <u>Zone</u>	<u>Cust</u> <u>Dev#</u>	<u>Address/</u> <u>Zone No.</u>	<u>Service</u> <u>Performed</u>	<u>Test</u> <u>Result</u>
SD	48 Salem Street	5th	Near Apt 514			M1-5	Tested	Passed
SSA	48 Salem Street	6th	Center Stairwell	7			Tested	Passed
ID	48 Salem Street	6th	Center Stairwell (FT)	8			Tested	Passed
Electrical Test Only								
SD	48 Salem Street	6th	Center Stairwell (Over Stairs)			M1-6	Tested	Passed
SD	48 Salem Street	6th	Center Stairwell (Walkway)			M1-6	Tested	Passed
SSA	48 Salem Street	6th	Exit near Apt 605	7			Tested	Passed
SSA	48 Salem Street	6th	Exit near Apt 614	7			Tested	Passed
SD	48 Salem Street	6th	Near Apt 601			M1-6	Tested	Passed
SD	48 Salem Street	6th	Near Apt 603			M1-6	Tested	Passed
SD	48 Salem Street	6th	Near Apt 605			M1-6	Tested	Passed
SD	48 Salem Street	6th	Near Apt 608			M1-6	Tested	Passed
SD	48 Salem Street	6th	Near Apt 610			M1-6	Tested	Passed
SD	48 Salem Street	6th	Near Apt 612			M1-6	Tested	Passed
SD	48 Salem Street	6th	Near Apt 614			M1-6	Tested	Passed
SD	48 Salem Street	6th	Stairwell near Apt 605			M1-6	Tested	Passed
SD	48 Salem Street	6th	Stairwell near Apt 614			M1-6	Tested	Passed
SSA	48 Salem Street	Gnd	Exit Near Apt 03	1			Tested	Passed
D	48 Salem Street	Gnd	Mechanical/Trash Room (FT)	11			Tested	Passed
Electrical Test Only								
SD	48 Salem Street	Gnd	Near Apt 01			M1-7	Tested	Passed
SD	48 Salem Street	Gnd	Near Apt 02			M1-7	Tested	Passed
SD	48 Salem Street	Gnd	Near Apt 03			M1-7	Tested	Passed
SD	48 Salem Street	Gnd	Rear Entry Vestibule			M1-7	Tested	Passed
SSA	48 Salem Street	Gnd	Rear Entry Vestibule	1			Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INDICATING DEVICES

SUMMARY TEST RESULTS

<u>Dev. Type</u>	<u>Description</u>	<u>Total</u>	<u>Number Tested</u>	<u>Number Failed</u>	<u>Number Not Tested</u>
A/V	Audio/Visual Signal Device	108	108	1	0
ANNC	Annunciator	2	2	0	0
ASIG	Audible Signal	130	129	0	1
VSIG	Visual Only Signal	2	2	0	0

DETAIL TEST RESULTS

<u>Dev Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust Zone</u>	<u>Cust Dev#</u>	<u>Address/ Zone No.</u>	<u>Service Performed</u>	<u>Test Result</u>
SIG	21 School Street	1st	Apt. 101				Tested	Passed
SIG	21 School Street	1st	Apt. 102				Tested	Passed
SIG	21 School Street	1st	Apt. 103				Tested	Passed
SIG	21 School Street	1st	Apt. 104				Tested	Passed
SIG	21 School Street	1st	Apt. 105				Tested	Passed
SIG	21 School Street	1st	Apt. 106				Tested	Passed
SIG	21 School Street	1st	Apt. 107				Tested	Passed
SIG	21 School Street	1st	Apt. 108				Tested	Passed
SIG	21 School Street	1st	Apt. 109				Tested	Passed
SIG	21 School Street	1st	Apt. 110				Tested	Passed
SIG	21 School Street	1st	Apt. 111				Tested	Passed
SIG	21 School Street	1st	Apt. 112				Tested	Passed
/V	21 School Street	1st	Hallway near 101				Tested	Passed
/V	21 School Street	1st	Hallway near 103				Tested	Passed
/V	21 School Street	1st	Hallway near 105				Tested	Passed
/V	21 School Street	1st	Hallway near 108				Tested	Passed
/V	21 School Street	1st	Hallway near 109				Tested	Passed
/V	21 School Street	1st	Hallway near 111				Tested	Passed
NNC	21 School Street	1st	Main Entry				Tested	Passed
SIG	21 School Street	2nd	Apt. 201				Tested	Passed
SIG	21 School Street	2nd	Apt. 202				Tested	Passed
SIG	21 School Street	2nd	Apt. 203				Tested	Passed
SIG	21 School Street	2nd	Apt. 204				Tested	Passed
SIG	21 School Street	2nd	Apt. 205				Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INDICATING DEVICES

DETAIL TEST RESULTS

<u>Dev</u> <u>Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust</u> <u>Zone</u>	<u>Cust</u> <u>Dev#</u>	<u>Address/</u> <u>Zone No.</u>	<u>Service</u> <u>Performed</u>	<u>Test</u> <u>Result</u>
\SIG	21 School Street	2nd	Apt. 206				Tested	Passed
\SIG	21 School Street	2nd	Apt. 207				Tested	Passed
\SIG	21 School Street	2nd	Apt. 208				Tested	Passed
\SIG	21 School Street	2nd	Apt. 209				Tested	Passed
\SIG	21 School Street	2nd	Apt. 210				Tested	Passed
\SIG	21 School Street	2nd	Apt. 211				Tested	Passed
\SIG	21 School Street	2nd	Apt. 212				Tested	Passed
\V	21 School Street	2nd	Hallway near 201				Tested	Passed
\V	21 School Street	2nd	Hallway near 203				Tested	Passed
\V	21 School Street	2nd	Hallway near 205				Tested	Passed
\V	21 School Street	2nd	Hallway near 208				Tested	Passed
\V	21 School Street	2nd	Hallway near 211				Tested	Passed
\SIG	21 School Street	3rd	Apt. 301				Tested	Passed
\SIG	21 School Street	3rd	Apt. 302				Not Tested	
Access could not be gained								
\SIG	21 School Street	3rd	Apt. 303				Tested	Passed
\SIG	21 School Street	3rd	Apt. 304				Tested	Passed
\SIG	21 School Street	3rd	Apt. 305				Tested	Passed
\SIG	21 School Street	3rd	Apt. 306				Tested	Passed
\SIG	21 School Street	3rd	Apt. 307				Tested	Passed
\SIG	21 School Street	3rd	Apt. 308				Tested	Passed
\V	21 School Street	3rd	Hallway near 301				Tested	Passed
\V	21 School Street	3rd	Hallway near 303				Tested	Passed
\V	21 School Street	3rd	Hallway near 305				Tested	Passed
\V	21 School Street	3rd	Hallway near 307				Tested	Passed
\SIG	21 School Street	Gnd	Apt. 1				Tested	Passed
\SIG	21 School Street	Gnd	Apt. 2				Tested	Passed
\SIG	21 School Street	Gnd	Apt. 3				Tested	Passed
\SIG	21 School Street	Gnd	Apt. 4				Tested	Passed
\SIG	21 School Street	Gnd	Apt. 5				Tested	Passed
\V	21 School Street	Gnd	Boiler Room				Tested	Passed
\V	21 School Street	Gnd	Hallway near 2				Tested	Passed
\V	21 School Street	Gnd	Hallway near 5				Tested	Passed
\SIG	240 Danforth Street	1st	Apt. 101				Tested	Passed
\SIG	240 Danforth Street	1st	Apt. 102				Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INDICATING DEVICES

DETAIL TEST RESULTS

<u>Dev</u> <u>Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust</u> <u>Zone</u>	<u>Cust</u> <u>Dev#</u>	<u>Address/</u> <u>Zone No.</u>	<u>Service</u> <u>Performed</u>	<u>Test</u> <u>Result</u>
∩SIG	240 Danforth Street	1st	Apt. 103				Tested	Passed
∩SIG	240 Danforth Street	1st	Apt. 104				Tested	Passed
∩SIG	240 Danforth Street	1st	Apt. 105				Tested	Passed
∩SIG	240 Danforth Street	1st	Apt. 106				Tested	Passed
∩SIG	240 Danforth Street	1st	Apt. 107				Tested	Passed
∩SIG	240 Danforth Street	1st	Apt. 108				Tested	Passed
∩SIG	240 Danforth Street	1st	Apt. 109				Tested	Passed
∩SIG	240 Danforth Street	1st	Apt. 110				Tested	Passed
∩NNC	240 Danforth Street	1st	Entry near Trash Chute				Tested	Passed
/V	240 Danforth Street	1st	Hallway near 104				Tested	Passed
/V	240 Danforth Street	1st	Hallway near 106				Tested	Passed
/V	240 Danforth Street	1st	Hallway near 108				Tested	Passed
/V	240 Danforth Street	1st	Hallway near 110				Tested	Passed
/V	240 Danforth Street	1st	Hallway near Trash Chute				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 201				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 202				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 203				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 204				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 205				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 206				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 207				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 208				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 209				Tested	Passed
.SIG	240 Danforth Street	2nd	Apt. 210				Tested	Passed
/V	240 Danforth Street	2nd	Hallway near Trash Chute				Tested	Passed
/V	240 Danforth Street	2nd	Hallway near 204				Tested	Passed
/V	240 Danforth Street	2nd	Hallway near 206				Tested	Passed
/V	240 Danforth Street	2nd	Hallway near 208				Tested	Passed
/V	240 Danforth Street	2nd	Hallway near 210				Tested	Passed
SIG	240 Danforth Street	3rd	Apt. 301				Tested	Passed
SIG	240 Danforth Street	3rd	Apt. 302				Tested	Passed
SIG	240 Danforth Street	3rd	Apt. 303				Tested	Passed
SIG	240 Danforth Street	3rd	Apt. 304				Tested	Passed
SIG	240 Danforth Street	3rd	Apt. 305				Tested	Passed
SIG	240 Danforth Street	3rd	Apt. 306				Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INDICATING DEVICES

DETAIL TEST RESULTS

<u>Dev</u> <u>Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust</u> <u>Zone</u>	<u>Cust</u> <u>Dev#</u>	<u>Address/</u> <u>Zone No.</u>	<u>Service</u> <u>Performed</u>	<u>Test</u> <u>Result</u>
\SIG	240 Danforth Street	3rd	Apt. 307				Tested	Passed
\SIG	240 Danforth Street	3rd	Apt. 308				Tested	Passed
\SIG	240 Danforth Street	3rd	Apt. 309				Tested	Passed
\SIG	240 Danforth Street	3rd	Apt. 310				Tested	Passed
\V	240 Danforth Street	3rd	Hallway near 304				Tested	Passed
\V	240 Danforth Street	3rd	Hallway near 306				Tested	Passed
\V	240 Danforth Street	3rd	Hallway near 308				Tested	Passed
\V	240 Danforth Street	3rd	Hallway near 310				Tested	Passed
\V	240 Danforth Street	3rd	Hallway near Trash Chute				Tested	Passed
\V	240 Danforth Street	Gnd	Boiler Room				Tested	Passed
\SIG	48 Salem Street	1st	Apt. 101				Tested	Passed
\SIG	48 Salem Street	1st	Apt. 102				Tested	Passed
\SIG	48 Salem Street	1st	Apt. 103				Tested	Passed
\SIG	48 Salem Street	1st	Apt. 104				Tested	Passed
\SIG	48 Salem Street	1st	Apt. 105				Tested	Passed
\SIG	48 Salem Street	1st	Apt. 106				Tested	Passed
\SIG	48 Salem Street	1st	Apt. 107				Tested	Passed
\V	48 Salem Street	1st	Center Stairwell				Tested	Passed
\V	48 Salem Street	1st	Hallway by Apt 101				Tested	Passed
\V	48 Salem Street	1st	Hallway by Apt 102				Tested	Passed
\V	48 Salem Street	1st	Hallway by Apt 103				Tested	Passed
\V	48 Salem Street	1st	Hallway by Apt 104				Tested	Passed
\V	48 Salem Street	1st	Hallway by Apt 105				Tested	Passed
\V	48 Salem Street	1st	Hallway by Apt 106				Tested	Passed
\V	48 Salem Street	1st	Hallway by Apt 107				Tested	Passed
.SIG	48 Salem Street	2nd	Apt. 201				Tested	Passed
.SIG	48 Salem Street	2nd	Apt. 202				Tested	Passed
.SIG	48 Salem Street	2nd	Apt. 203				Tested	Passed
.SIG	48 Salem Street	2nd	Apt. 204				Tested	Passed
.SIG	48 Salem Street	2nd	Apt. 205				Tested	Passed
.SIG	48 Salem Street	2nd	Apt. 206				Tested	Passed
.SIG	48 Salem Street	2nd	Apt. 207				Tested	Passed
\V	48 Salem Street	2nd	Center Stairwell				Tested	Passed
\V	48 Salem Street	2nd	Hallway by Apt 201				Tested	Passed
\V	48 Salem Street	2nd	Hallway by Apt 202				Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INDICATING DEVICES

DETAIL TEST RESULTS

<u>Dev</u> <u>Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust</u> <u>Zone</u>	<u>Cust</u> <u>Dev#</u>	<u>Address/</u> <u>Zone No.</u>	<u>Service</u> <u>Performed</u>	<u>Test</u> <u>Result</u>
VV	48 Salem Street	2nd	Hallway by Apt 203				Tested	Passed
VV	48 Salem Street	2nd	Hallway by Apt 204				Tested	Passed
VV	48 Salem Street	2nd	Hallway by Apt 205				Tested	Passed
VV	48 Salem Street	2nd	Hallway by Apt 206				Tested	Passed
VV	48 Salem Street	2nd	Hallway by Apt 207				Tested	Passed
ASIG	48 Salem Street	3rd	Apt. 301				Tested	Passed
ASIG	48 Salem Street	3rd	Apt. 302				Tested	Passed
VV	48 Salem Street	3rd	Apt. 303 (BR)				Tested	Passed
VV	48 Salem Street	3rd	Apt. 303 (LR)				Tested	Passed
VV	48 Salem Street	3rd	Apt. 303 (RR)				Tested	Passed
ASIG	48 Salem Street	3rd	Apt. 304				Tested	Passed
ASIG	48 Salem Street	3rd	Apt. 305				Tested	Passed
ASIG	48 Salem Street	3rd	Apt. 306				Tested	Passed
ASIG	48 Salem Street	3rd	Apt. 307				Tested	Passed
ASIG	48 Salem Street	3rd	Apt. 308				Tested	Passed
ASIG	48 Salem Street	3rd	Apt. 309				Tested	Passed
ASIG	48 Salem Street	3rd	Apt. 310				Tested	Passed
VV	48 Salem Street	3rd	Boiler Room				Tested	Passed
VV	48 Salem Street	3rd	Center Stairwell				Tested	Passed
VV	48 Salem Street	3rd	Foyer by Laundry				Tested	Passed
VV	48 Salem Street	3rd	Hallway by Apt 301				Tested	Passed
VV	48 Salem Street	3rd	Hallway by Apt 303				Tested	Passed
VV	48 Salem Street	3rd	Hallway by Apt 306				Tested	Passed
VV	48 Salem Street	3rd	Hallway by Apt 308				Tested	Failed
							A/V visual failure	
VV	48 Salem Street	3rd	Hallway by Apt 310				Tested	Passed
VV	48 Salem Street	3rd	Hallway by Boiler Room				Tested	Passed
VV	48 Salem Street	3rd	Hallway near Office				Tested	Passed
VV	48 Salem Street	3rd	Laundry Room				Tested	Passed
VV	48 Salem Street	3rd	Maintenance Shop				Tested	Passed
SIG	48 Salem Street	3rd	Restroom by Laundry (Left)				Tested	Passed
SIG	48 Salem Street	3rd	Restroom by Laundry (Right)				Tested	Passed
VV	48 Salem Street	4th	Apt. 401 (BR1)				Tested	Passed
VV	48 Salem Street	4th	Apt. 401 (BR2)				Tested	Passed
VV	48 Salem Street	4th	Apt. 401 (LR)				Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INDICATING DEVICES

DETAIL TEST RESULTS

<u>Dev Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust Zone</u>	<u>Cust Dev#</u>	<u>Address/ Zone No.</u>	<u>Service Performed</u>	<u>Test Result</u>
A/V	48 Salem Street	4th	Apt. 401 (RR)				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 402				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 403				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 404				Tested	Passed
A/V	48 Salem Street	4th	Apt. 405 (BR)				Tested	Passed
A/V	48 Salem Street	4th	Apt. 405 (LR)				Tested	Passed
A/V	48 Salem Street	4th	Apt. 405 (RR)				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 406				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 407				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 408				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 409				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 410				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 411				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 412				Tested	Passed
ASIG	48 Salem Street	4th	Apt. 413				Tested	Passed
V/V	48 Salem Street	4th	Apt. 414 (BR)				Tested	Passed
V/V	48 Salem Street	4th	Apt. 414 (LR)				Tested	Passed
V/V	48 Salem Street	4th	Apt. 414 (RR)				Tested	Passed
V/V	48 Salem Street	4th	Center Stairwell				Tested	Passed
V/V	48 Salem Street	4th	Hallway by Apt 401				Tested	Passed
V/V	48 Salem Street	4th	Hallway by Apt 405				Tested	Passed
V/V	48 Salem Street	4th	Hallway by Apt 408				Tested	Passed
V/V	48 Salem Street	4th	Hallway by Apt 410				Tested	Passed
V/V	48 Salem Street	4th	Hallway by Apt 412				Tested	Passed
V/V	48 Salem Street	4th	Hallway by Apt 414				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 501				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 502				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 503				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 504				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 505				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 506				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 507				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 508				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 509				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 510				Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INDICATING DEVICES

DETAIL TEST RESULTS

<u>Dev Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust Zone</u>	<u>Cust Dev#</u>	<u>Address/ Zone No.</u>	<u>Service Performed</u>	<u>Test Result</u>
ASIG	48 Salem Street	5th	Apt. 511				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 512				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 513				Tested	Passed
ASIG	48 Salem Street	5th	Apt. 514				Tested	Passed
A/V	48 Salem Street	5th	Center Stairwell				Tested	Passed
A/V	48 Salem Street	5th	Hallway by Apt 501				Tested	Passed
A/V	48 Salem Street	5th	Hallway by Apt 505				Tested	Passed
A/V	48 Salem Street	5th	Hallway by Apt 508				Tested	Passed
A/V	48 Salem Street	5th	Hallway by Apt 510				Tested	Passed
A/V	48 Salem Street	5th	Hallway by Apt 512				Tested	Passed
A/V	48 Salem Street	5th	Hallway by Apt 514				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 601				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 602				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 603				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 604				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 605				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 606				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 607				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 608				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 609				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 610				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 611				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 612				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 613				Tested	Passed
ASIG	48 Salem Street	6th	Apt. 614				Tested	Passed
A/V	48 Salem Street	6th	Center Stairwell				Tested	Passed
A/V	48 Salem Street	6th	Hallway by Apt 601				Tested	Passed
A/V	48 Salem Street	6th	Hallway by Apt 605				Tested	Passed
A/V	48 Salem Street	6th	Hallway by Apt 608				Tested	Passed
A/V	48 Salem Street	6th	Hallway by Apt 610				Tested	Passed
A/V	48 Salem Street	6th	Hallway by Apt 612				Tested	Passed
A/V	48 Salem Street	6th	Hallway by Apt 614				Tested	Passed
A/V	48 Salem Street	Gnd	Apt. 1 (LBR)				Tested	Passed
A/V	48 Salem Street	Gnd	Apt. 1 (LR)				Tested	Passed
A/V	48 Salem Street	Gnd	Apt. 1 (RBR)				Tested	Passed

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

ALARM INDICATING DEVICES

DETAIL TEST RESULTS

<u>Dev</u> <u>Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust</u> <u>Zone</u>	<u>Cust</u> <u>Dev#</u>	<u>Address/</u> <u>Zone No.</u>	<u>Service</u> <u>Performed</u>	<u>Test</u> <u>Result</u>
√V	48 Salem Street	Gnd	Apt. 1 (RR)				Tested	Passed
√V	48 Salem Street	Gnd	Apt. 2 (LBR)				Tested	Passed
√V	48 Salem Street	Gnd	Apt. 2 (LR)				Tested	Passed
√V	48 Salem Street	Gnd	Apt. 2 (RBR)				Tested	Passed
√V	48 Salem Street	Gnd	Apt. 2 (RR)				Tested	Passed
√SIG	48 Salem Street	Gnd	Apt. 3				Tested	Passed
√V	48 Salem Street	Gnd	Hallway by Apt 01				Tested	Passed
√V	48 Salem Street	Gnd	Hallway by Apt 02				Tested	Passed
√V	48 Salem Street	Gnd	Hallway by Apt 03				Tested	Passed
√V	48 Salem Street	Gnd	Rear Entry Vestibule				Tested	Passed

SITE: Danforth Heights

SUPERVISORY DEVICES

SUMMARY TEST RESULTS

<u>Dev. Type</u>	<u>Description</u>	<u>Total</u>	<u>Number Tested</u>	<u>Number Failed</u>	<u>Number Not Tested</u>
DIAL	Telephone Dialer	1	1	1	0

DETAIL TEST RESULTS

<u>Dev Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust Zone</u>	<u>Cust Dev#</u>	<u>Address/ Zone No.</u>	<u>Service Performed</u>	<u>Test Result</u>
DIAL	21 School Street	Gnd	Boiler Room Inside FACP				Tested	Failed
						Secondary Phone Line Inactive		

SITE: Danforth Heights

CONTROL/AUXILIARY DEVICES

SUMMARY TEST RESULTS

<u>Dev. Type</u>	<u>Description</u>	<u>Total</u>	<u>Number Tested</u>	<u>Number Failed</u>	<u>Number Not Tested</u>
FFPH	Fire Fighter Phone Cabinet	1	1	1	0
FFPJ	Fire Fighter Phone Jack	17	17	0	0

DETAIL TEST RESULTS

<u>Dev Type</u>	<u>Building</u>	<u>Floor</u>	<u>Area</u>	<u>Cust Zone</u>	<u>Cust Dev#</u>	<u>Address/ Zone No.</u>	<u>Service Performed</u>	<u>Test Result</u>
FPJ	48 Salem Street	1st	Center Stairwell				Tested	Passed
FPJ	48 Salem Street	1st	West Stairwell				Tested	Passed
FPJ	48 Salem Street	2nd	Center Stairwell				Tested	Passed
FPJ	48 Salem Street	2nd	West Stairwell				Tested	Passed
FPJ	48 Salem Street	3rd	Center Stairwell				Tested	Passed
FPJ	48 Salem Street	3rd	East Stairwell				Tested	Passed
FPJ	48 Salem Street	3rd	West Stairwell				Tested	Passed
FPJ	48 Salem Street	4th	Center Stairwell				Tested	Passed
FFPH	48 Salem Street	4th	Center Stairwell (Fire Fighters Phone)				Tested	Failed
							Faulty Handset; Replace	
FPJ	48 Salem Street	4th	East Stairwell				Tested	Passed
FPJ	48 Salem Street	4th	West Stairwell				Tested	Passed
FPJ	48 Salem Street	5th	Center Stairwell				Tested	Passed
FPJ	48 Salem Street	5th	East Stairwell				Tested	Passed
FPJ	48 Salem Street	5th	West Stairwell				Tested	Passed
FPJ	48 Salem Street	6th	Center Stairwell				Tested	Passed
FPJ	48 Salem Street	6th	East Stairwell				Tested	Passed
FPJ	48 Salem Street	6th	West Stairwell				Tested	Passed
FPJ	48 Salem Street	Gnd	Center Stairwell				Tested	Passed

SITE: Danforth Heights

SENSITIVITY TESTING

SUMMARY TEST RESULTS

<u>Dev. Type</u>	<u>Floor</u>	<u>Area</u>	<u>Cust Zone</u>	<u>Cust Dev#</u>	<u>Address/ Zone No.</u>	<u>Mfg. Range</u>	<u>Prior Test</u>	<u>Current Test</u>	<u>Test Result</u>
Building: 21 School Street									
PSD	1st	Hallway near 101	4				N/A	N/A	
PSD	1st	Hallway near 103	4				N/A	N/A	
PSD	1st	Hallway near 105	4				N/A	N/A	
PSD	1st	Hallway near 107	4				N/A	N/A	
PSD	1st	Hallway near 108	4				N/A	N/A	
PSD	1st	Hallway near 109	4				N/A	N/A	
PSD	1st	Hallway near 111	4				N/A	N/A	
PSD	2nd	Hallway near 201	6				N/A	N/A	
PSD	2nd	Hallway near 203	6				N/A	N/A	
PSD	2nd	Hallway near 205	6				N/A	N/A	
PSD	2nd	Hallway near 207	6				N/A	N/A	
PSD	2nd	Hallway near 208	6				N/A	N/A	
PSD	2nd	Hallway near 209	6				N/A	N/A	
PSD	2nd	Hallway near 211	6				N/A	N/A	
PSD	2nd	Stair near 211	6				N/A	N/A	
PSD	3rd	Hallway near 301	8				N/A	N/A	
PSD	3rd	Hallway near 303	8				N/A	N/A	
PSD	3rd	Hallway near 305	8				N/A	N/A	
PSD	3rd	Hallway near 307	8				N/A	N/A	
PSD	3rd	Hallway near Trash Chute	8				N/A	N/A	
PSD	3rd	Stair near 301	8				N/A	N/A	
PSD	3rd	Stairwell near 307	8				N/A	N/A	
PSD	Gnd	Hallway near 2	2				N/A	N/A	
PSD	Gnd	Hallway near 3	2				N/A	N/A	
PSD	Gnd	Hallway near 5	2				N/A	N/A	
Building: 240 Danforth Street									
PSD	1st	Hallway near 104	2				N/A	N/A	
PSD	1st	Hallway near 106	2				N/A	N/A	
PSD	1st	Hallway near 108	2				N/A	N/A	
PSD	1st	Hallway near 110	2				N/A	N/A	
PSD	1st	Hallway near Trash Chute	2				N/A	N/A	
PSD	2nd	Hallway near 204	4				N/A	N/A	
PSD	2nd	Hallway near 206	4				N/A	N/A	
PSD	2nd	Hallway near 208	4				N/A	N/A	
PSD	2nd	Hallway near 210	4				N/A	N/A	

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

SENSITIVITY TESTING

SUMMARY TEST RESULTS

<u>Dev. Type</u>	<u>Floor Area</u>	<u>Cust Zone</u>	<u>Cust Dev#</u>	<u>Address/ Zone No.</u>	<u>Mfg. Range</u>	<u>Prior Test</u>	<u>Current Test</u>	<u>Test Result</u>
PSD	2nd Hallway near Trash Chute	4				N/A	N/A	
PSD	3rd Hallway near 304	6				N/A	N/A	
PSD	3rd Hallway near 306	6				N/A	N/A	
PSD	3rd Hallway near 308	6				N/A	N/A	
PSD	3rd Hallway near 310	6				N/A	N/A	
PSD	3rd Hallway near Trash Chute	6				N/A	N/A	
PSD	3rd Stairwell near 310	6				N/A	N/A	
PSD	3rd Stairwell near Trash Chute	6				N/A	N/A	
Building: 48 Salem Street								
PSD	1st Center Stairwell			M1-1		N/A	N/A	
PSD	1st Near Apt 101			M1-1		N/A	N/A	
PSD	1st Near Apt 102			M1-1		N/A	N/A	
PSD	1st Near Apt 103			M1-1		N/A	N/A	
PSD	1st Near Apt 104			M1-1		N/A	N/A	
PSD	1st Near Apt 105			M1-1		N/A	N/A	
PSD	1st Near Apt 106			M1-1		N/A	N/A	
PSD	1st Near Apt 107			M1-1		N/A	N/A	
PSD	2nd Center Stairwell			M1-2		N/A	N/A	
PSD	2nd Near Apt 201			M1-2		N/A	N/A	
PSD	2nd Near Apt 202			M1-2		N/A	N/A	
PSD	2nd Near Apt 203			M1-2		N/A	N/A	
PSD	2nd Near Apt 204			M1-2		N/A	N/A	
PSD	2nd Near Apt 205			M1-2		N/A	N/A	
PSD	2nd Near Apt 206			M1-2		N/A	N/A	
PSD	2nd Near Apt 207			M1-2		N/A	N/A	
PSD	3rd Center Stairwell			M1-3		N/A	N/A	
PSD	3rd Near Apt 301			M1-3		N/A	N/A	
PSD	3rd Near Apt 302			M1-3		N/A	N/A	
PSD	3rd Near Apt 303			M1-3		N/A	N/A	
PSD	3rd Near Apt 306			M1-3		N/A	N/A	
PSD	3rd Near Apt 308			M1-3		N/A	N/A	
PSD	3rd Near Apt 310			M1-3		N/A	N/A	
PSD	3rd Near Boiler Room			M1-3		N/A	N/A	
PSD	4th Center Stairwell			M1-4		N/A	N/A	
PSD	4th Near Apt 401			M1-4		N/A	N/A	
PSD	4th Near Apt 403			M1-4		N/A	N/A	

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

PAGE 24

SITE: Danforth Heights



SENSITIVITY TESTING

SUMMARY TEST RESULTS

<u>Dev.</u>	<u>Zone</u>	<u>Cust</u>	<u>Cust</u>	<u>Address/</u>	<u>Mfg. Range</u>	<u>Prior</u>	<u>Current</u>	<u>Test</u>
<u>Type</u>	<u>Floor</u>	<u>Area</u>	<u>Dev#</u>	<u>Zone No.</u>		<u>Test</u>	<u>Test</u>	<u>Result</u>
PSD	4th	Near Apt 405		M1-4		N/A	N/A	
PSD	4th	Near Apt 408		M1-4		N/A	N/A	
PSD	4th	Near Apt 410		M1-4		N/A	N/A	
PSD	4th	Near Apt 412		M1-4		N/A	N/A	
PSD	4th	Near Apt 414		M1-4		N/A	N/A	
PSD	5th	Center Stairwell		M1-5		N/A	N/A	
PSD	5th	Near Apt 501		M1-5		N/A	N/A	
PSD	5th	Near Apt 503		M1-5		N/A	N/A	
PSD	5th	Near Apt 505		M1-5		N/A	N/A	
PSD	5th	Near Apt 508		M1-5		N/A	N/A	
PSD	5th	Near Apt 510		M1-5		N/A	N/A	
PSD	5th	Near Apt 512		M1-5		N/A	N/A	
PSD	5th	Near Apt 514		M1-5		N/A	N/A	
PSD	6th	Center Stairwell (Over Stairs)		M1-6		N/A	N/A	
PSD	6th	Center Stairwell (Walkway)		M1-6		N/A	N/A	
PSD	6th	Near Apt 601		M1-6		N/A	N/A	
PSD	6th	Near Apt 603		M1-6		N/A	N/A	
PSD	6th	Near Apt 605		M1-6		N/A	N/A	
PSD	6th	Near Apt 608		M1-6		N/A	N/A	
PSD	6th	Near Apt 610		M1-6		N/A	N/A	
PSD	6th	Near Apt 612		M1-6		N/A	N/A	
PSD	6th	Near Apt 614		M1-6		N/A	N/A	
PSD	6th	Stairwell near Apt 605		M1-6		N/A	N/A	
PSD	6th	Stairwell near Apt 614		M1-6		N/A	N/A	
PSD	Gnd	Near Apt 01		M1-7		N/A	N/A	
PSD	Gnd	Near Apt 02		M1-7		N/A	N/A	
PSD	Gnd	Near Apt 03		M1-7		N/A	N/A	
PSD	Gnd	Rear Entry Vestibule		M1-7		N/A	N/A	

**SimplexGrinnell
FIRE ALARM INSPECTION REPORT**

SITE: Danforth Heights

<u>Customer</u>	<u>Date</u>
 John Linscott	<u>3-27-19</u> Date
 Chuck Baickle	<u>3/29/19</u> Date
<u>Alex Larrabee</u>	<u>Date</u>
<u>Chuck Rice</u>	<u>Date</u>

IF YOU HAVE ANY QUESTIONS REGARDING THIS REPORT, PLEASE CONTACT

Vicky Allen Branch Service Manager

**Phone: (207) 842-6440
Address: 30 Thomas Drive
Westbrook, ME 04092**