

Table Va

February 18, 1960

Hr. James Talbot 40 Salem Street Fortland, Maine

Dear Mr. Talbot:

Re: 42-44 Salem Street

We recently made an inspection of the property owned by you at 42-44 Salem Street, "ortland, "bir: As a small of the inspection, you are hereby ordered to correct the following substandard housing conditions:

84 STRUCTURAL Repair and put in good order all dilapidated and harardous parts of the structure as follows :

a. Repair or replace the missing downspouts on the front

side of the structure. Repair or replace the loose, worm, proken, collapidated, and hazardous parts of the treads on the cellar stairs.

Replace the broken window pane on the right sice of the cellar.

Repair or replace the cracked, loose, or missing plaster on the wall under the mink in the bitchen of 44 Salen Street.

The above montioned conflictions are in violation of the City Ordinance, MINIDAM STANDARDS FOR CONTINUED OCCUPANCY, and AUTHORITY TO VACATE BILL INCO, and must be corrected on or before

Very truly yours,

Norman M. Winch, P. 3. Acting Health Director

∄′:

Gordon E. Martin Housing Supervisor

GEM: ew

W -81 C C SE ZONE

## Class of Building or Type of Structure

## APPLICATION FOR PERMIT

Third Class Portland, Maine, June 14, 1955 008(2% # 15 1955

CITY of PURTLAND

To the INSPECTOR OF BUILDINGS, FORTLAND, MAINE

demolish install the following building structure equipment and Zoning Ordinance of the City of Portland, plans and us:
Within Fire Limits? Dist. No
m St. Telephone
Telephone
Telephone
nsNo. of sheets
No. families 2
No. families 2
e of roofRoofing
Fee \$ .50

## General Description of New Work

To demolish existing 1-story frame ell on rear of building. To clapboard end of building

CLKILICATE OF OCCUPANCY

It is understood that this permit does not include installation of 'wating apparatus which is to be laken out Strate of the laken of the laken out Strate out

the nan e of the heating conti	actor. PERMIT TO	D BE ISSUED TO	owner		, ,	
Is any plumbing involved Is connection to be made	in this work?to public sewer?	If not, w	ectrical work invehat is proposed:	for sewage?		
Has septic tank notice bee	:n sent?	Form no	tice sert?			
Height average grade to t	op if plate	Height avera	nce prade to high	est point of roof		
Size, front dep	ries solid or fi	ssolid or filled land?earth or rock?				
Material of foundation		Thickness, top	bottom	œllar	*************************	
Material of underpinning	······································	Height		Thickness		
Kind of roof	Rise per foot	Roef cov	ering			
No. of chimneys	Material of chim	neys of lining	K	ind of heat	fuel	
Framing lumber-Kind	*** , *** *** *** *** ****	Dressed o	or full size?		lys approach to the section confidences of	
Corner posts	.SillsGir	t or ledger board?	** **********	Size		
Girders Size		ınder girdera	Size	Max. on centers		
Studs (outside walls and c	arrying partitions) 2x-	4-16" O. C. Bridging	in every floor ar	nd flat roof span	over 8 feet.	
Joists and lafters:	1st floor	, 2nd	, 3rd	, roo	ſ	
On centers:	1st floor	, 2nd	3rd	, roo	f	
Maximum span:	1st floor	2nd	, 3rd	, roo	f	
If one story building with						
		T(		_		
No. cars now accommodat	,	If a Garage be accommodated.			accommodated	
Will automobile repairing	be do.ie other than mi	inor repairs to cars ha	bitually stored in	n the proposed bu	ilding?	
PROVED:		$\neg$	Miscellaneous			
1107111.		Will work require disturbing of any tree on a public street? no				
paracalistica de la constitución		· ·		-	erson competent to	
		see that the S	tate and City r	•	taining thereto un	

INSPECTION COPY

NOTES Staking C .. Notice Final Notif. Form Check Notice Certiof Occupancy issued Notif. closing-in or the story of the lam, obstalle a. Ln' 12384 لعدوبهد . 3 61 ANTIOTEN IL ्रे <u>करा राज्यकात राज</u> i3 \*\* r1.123 100 ENT AND I HARESTAND